

Fault report - SD50B-2026-10279 - 2026-06-17

Document fault-report-sd50b-2026-10279-12 · revision 1 · effective 2026-06-17

Machine type:

Reported symptom

Machine SD50B-2026-10279 at City Hospital is showing E-101 (Charger communication lost) repeatedly. It clears if the machine is switched off and on, but comes back within the hour.

Site assessment

Suspected filter blockage, but nobody on site is trained to remove it.

Status

Machine taken out of service and tagged. Awaiting engineer attendance.