

Hangar Seven - 2026-06-11

Document handover-hangar-seven-2026-06-11-09 · revision 1 · effective 2026-06-11

Machine type:

Shift note

Quick one - SWR-120 was down for part of the shift, see below.

Observations

- Recovery tank smelled bad at the end of the run, probably not rinsed properly yesterday.

- Noticed a

Actions taken

- Logged it with the service desk, reference on the whiteboard.

- Nothing d

Outstanding

- Wants a filter check before the next long run.

- Please co

S. Petrov. Back Thursday.