

Safety data sheet: acidic descaling detergent

Document safety-detergent-sds-acidic · revision 1 · effective 2026-01-19

Hazard

A wet floor behind a machine with a worn squeegee is a slip hazard. It is created by the cleaning operation itself, which is why it is so often missed in a risk assessment.

Control measures

- Keep the charging area clear of ignition sources, including battery-powered tools.

- Decant co

Personal protective equipment

- Eye protection when decanting concentrate or working near a charging pack.

- Safety fo

In an emergency

- Spill of concentrate: contain with the spill kit, do not flush to drain, and report the volume. Diluted solution may be flushed; concentrate may not.

- Skin cont
minutes. D