

# Fault report - SD50B-2026-10279 - 2026-06-17

Document fault-report-sd50b-2026-10279-12 · revision 1 · effective 2026-06-17

Machine types: SD-50B

Item numbers: 1.512-341.0

Serial numbers: SD50B-2026-10279

Site: city-hospital

## Reported symptom

Machine SD50B-2026-10279 at City Hospital is showing E-101 (Charger communication lost) repeatedly. It clears if the machine is switched off and on, but comes back within the hour.

## Site assessment

Suspected filter blockage, but nobody on site is trained to remove it.

## Status

Machine taken out of service and tagged. Awaiting engineer attendance.