

Hangar Seven - 2026-05-06

Document handover-hangar-seven-2026-05-06-30 · revision 1 · effective 2026-05-06

Machine types: VS-75

Item numbers: 1.688-420.0

Serial numbers: VS75-2026-10415

Site: hangar-seven

Shift note

Handover notes, Hangar Seven. Nothing dramatic but a couple of things to watch.

Observations

- Left hand side broom seems to be missing bristles.
- Machine pulled slightly to the right all shift. Might be a deck adjustment.
- Noticed a rattle from the deck when reversing. Goes away at low speed.

Actions taken

- Cleared the debris from the brush deck, there was a lot of shrink wrap wound round.
- Emptied and rinsed the hopper, ran the filter shaker first.

Outstanding

- Please confirm the wear limit before changing anything, I am going from memory.
- Battery wants a full charge cycle, do not take it out on a short top-up.

A. Okafor, end of shift.