

Safety data sheet: acidic descaling detergent

Document safety-detergent-sds-acidic · revision 1 · effective 2026-01-19

Hazard

A wet floor behind a machine with a worn squeegee is a slip hazard. It is created by the cleaning operation itself, which is why it is so often missed in a risk assessment.

Control measures

- Keep the charging area clear of ignition sources, including battery-powered tools.
- Decant concentrate over a bund or a drip tray, never over an open floor.
- Isolate the battery before any work beyond the daily operator checks.
- Sound the horn at every blind corner and at every door.
- Charge only in the designated bay, with the ventilation running.

Personal protective equipment

- Eye protection when decanting concentrate or working near a charging pack.
- Safety footwear with a slip-resistant sole, since the operator walks the wet area.
- Nitrile gloves when handling concentrate or working on a battery.

In an emergency

- Spill of concentrate: contain with the spill kit, do not flush to drain, and report the volume. Diluted solution may be flushed; concentrate may not.
- Skin contact with concentrate: remove contaminated clothing and rinse with running water for at least fifteen minutes. Do not neutralise.
- Machine strike or near miss: stop the machine, isolate it, and report before continuing. A near miss on a ride-on machine is reportable.