

Dome-shaped - frame casting
crabs
Chain well
fox-tail bolts
5"
For working the gates 2 for each gate
CHAIN SHAFT
vertical drum pnlly
footstep spindle
Spindle box
MAN HOLE
drag hook
Drag chain 5/8"
3"
bevel wheel
Drums
3 5/8" spindle 2½"ϕ x 2½"
bevel pinion
18"ϕ spur-wheel
first power spindle
6"ϕ 2nd power spindle
2½" face