



<u>Pins</u>	<u>Wire</u>
1	Motor winding 1 (M+)
2	Motor winding 2 (M-)
3	Motor winding 3
4	Motor Shield (if available)