
(a) Engine failure: throttle drops to 0
Reported throttle (vfr_hud)
0.0
0.2
0.4
0.6
−20
−10
0
10
Time from fault onset (s)
(b) Rudder failure: servo output held at 1900
Servo output rc-out (PWM, μs)
1400
1500
1600
1700
1800
1900
rudder channel
aileron channel
−20
−10
0
10
Time from fault onset (s)