```
C:\>debug 3b.exe
-t
AX=076A BX=0000 CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=075A ES=075A SS=0769 CS=076B IP=0003
                                           NU UP EI PL NZ NA PO NC
076B:0003 8ED8
                      MOV
                              DS,AX
-t
AX-076A BX-0000 CX-002A DX-0000 SP-0000 BP-0000 SI-0000 DI-0000
DS=076A ES=075A SS=0769 CS=076B IP=0005
                                           NU UP EI PL NZ NA PO NC
076B:0005 B400
                      MOV
                              AH,00
-t
AX-006A BX-0000 CX-002A DX-0000 SP-0000 BP-0000 SI-0000 DI-0000
DS=076A ES=075A SS=0769 CS=076B IP=0007
                                           NU UP EI PL NZ NA PO NC
076B:0007 8B0E0500
                      MOV
                              CX,[0005]
                                                               DS:0005=0005
-t
AX=006A BX=0000 CX=0005 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
                SS=0769 CS=076B IP=000E
DS=076A ES=075A
                                           NU UP EI PL NZ NA PO NC
076B:000E 8A07
                      MOV
                              AL,[BX]
                                                               DS:0000=05
-t
AX=0005 BX=0000 CX=0005 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
                SS=0769 CS=076B
                                           NU UP EI PL NZ NA PO NC
DS=076A ES=075A
                                  IP=0010
                       INC
076B:0010 43
                              BX
-t
AX=0005 BX=0001 CX=0004 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A SS=0769 CS=076B IP=0010
                                           NU UP EI PL NZ NA PO NC
                       INC
                              BX
076B:0010 43
-t
AX=0005 BX=0002 CX=0004 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                SS=0769 CS=076B IP=0011
                                           NV UP EI PL NZ NA PO NC
                      CMP
                              AL,[BX]
076B:0011 3A07
                                                                DS:000Z=06
-t
AX=0005 BX=0002
                CX=0004 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A
                 SS=0769 CS=076B IP=0013
                                           NU UP EI NG NZ AC PE CY
076B:0013 7302
                              0017
                       JNB
-t
AX=0005 BX=0002 CX=0004 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=075A SS=0769 CS=076B IP=0015
                                           NV UP EI NG NZ AC PE CY
                              AL,[BX]
076B:0015 8607
                       XCHG
                                                                DS:0002=06
-t
```

	CX=0003 DX=0000 SP=0000 SS=0769 CS=076B IP=0010 INC BX	
	CX=0003 DX=0000 SP=0000 SS=0769 CS=076B IP=0011 CMP AL,[BX]	
DS=076A ES=075A	CX=0002 DX=0000 SP=0000 SS=0769 CS=076B IP=0011 CMP AL,[BX]	
	CX=0002 DX=0000 SP=0000 SS=0769 CS=076B IP=0013 JNB 0017	
DS=076A ES=075A	CX=0002 DX=0000 SP=0000 SS=0769 CS=076B IP=0015 XCHG AL,[BX]	
DS=076A ES=075A	CX=0001 DX=0000 SP=0000 SS=0769 CS=076B IP=0011 CMP AL,[BX]	
	CX=0001 DX=0000 SP=0000 SS=0769 CS=076B IP=0013 JNB 0017	
	CX=0001 DX=0000 SP=0000 SS=0769 CS=076B IP=0017 LOOP 0010	
	CX=0000 DX=0000 SP=0000 SS=0769 CS=076B IP=0019 INT 3	