```
C:\>debug 4a.exe
-t
AX=076A BX=0000 CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=075A ES=075A SS=0769 CS=076B IP=0003
                                           NU UP EI PL NZ NA PO NC
076B:0003 8ED8
                      MOV
                              DS, AX
-t
AX=076A BX=0000 CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
                SS=0769 CS=076B IP=0005
                                           NU UP EI PL NZ NA PO NC
DS=076A ES=075A
076B:0005 8ECO
                      MOV
                              ES, AX
-t
AX=076A BX=0000 CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=076A SS=0769 CS=076B IP=0007
                                           NU UP EI PL NZ NA PO NC
976B:0007 FC
                      CLD
-t
AX=076A BX=0000 CX=002A DX=0000 SP=0000
                                          BP=0000 SI=0000 DI=0000
DS=076A ES=076A SS=0769 CS=076B IP=0008
                                           NV UP EI PL NZ NA PO NC
976B:0008 8D3E0000
                      LEA
                              DI,[0000]
                                                                DS:0000=4E41
AX=076A BX=0000 CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
                SS=0769 CS=076B IP=000C
DS=076A ES=076A
                                           NV UP EI PL NZ NA PO NC
976B:000C A00700
                      MOV
                              AL,[0007]
                                                               DS:0007=23
-t
                CX=002A DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
AX=0723 BX=0000
                SS=0769 CS=076B IP=000F
DS=076A ES=076A
                                           NU UP EI PL NZ NA PO NC
976B:000F B91400
                      MOV
                              CX,0014
-t
AX=0723 BX=0000 CX=0014 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=076A SS=0769 CS=076B IP=0012
                                           NV UP EI PL NZ NA PO NC
976B:0012 B400
                      MOV
                              AH,00
-t
AX=0023 BX=0000 CX=0014 DX=0000 SP=0000 BP=0000 SI=0000 DI=0000
DS=076A ES=076A SS=0769 CS=076B IP=0014
                                           NV UP EI PL NZ NA PO NC
976B:0014 FZ
                      REPNZ
976B:0015 AE
                      SCASB
-t
AX=0023 BX=0000 CX=000D DX=0000 SP=0000 BP=0000 SI=0000 DI=0007
DS=076A ES=076A
                SS=0769 CS=076B IP=0016
                                           NU UP EI PL ZR NA PE NC
976B:0016 4F
                      DEC
                              DΙ
```

AX=0723 BX=0000 DS=076A ES=076A 076B:0012 B400 -t			BP=0000 SI=0000 DI=0000 NV UP EI PL NZ NA PO NC
AX=0023 BX=0000 DS=076A ES=076A 076B:0014 F2 976B:0015 AE -t	REPNZ		BP=0000 SI=0000 DI=0000 NV UP EI PL NZ NA PO NC
	SS=0769 CS=076B		BP=0000 SI=0000 DI=0007 NU UP EI PL ZR NA PE NC
	SS=0769 CS=076B	IP=0017	BP=0000 SI=0000 DI=0006 NU UP EI PL NZ NA PE NC
AX=0006 BX=0000 DS=076A ES=076A 976B:0019 CC	CX=000D DX=0000 SS=0769 CS=076B INT 3	SP=0000 IP=0019	BP=0000 SI=0000 DI=0006 NU UP EI PL NZ NA PE NC