

- 1.Must be RoHS compliant
- 2. Parts must be free of oil and debris

