
OSSM

Wiring Guide

V2.3 Board - V1.0.9

RESEARCH + DESIRE



Support

support@researchanddesire.com

Assembly instructions


ohai.researchanddesire.com/ossm

Actual size



Print at 100 % (actual size). Lay a part on its dashed outline to identify it.

Bolts



M6×12 Screw



M3×8 Screw

Hex keys




5 mm Hex key



2.5 mm Hex key

Parts


Electronics



1×
OSSM board




1×
Motor wiring harness




1×
24V power supply

3D printed




1×
PCB box



1×
PCB lid

Hardware



2×
M6×12 Screw



6×
M3×8 Screw

Tools


Required



2.5 mm
Hex key




5 mm Hex key



2 mm
Flat screwdriver

Recommended




Threadlocker
(blue 243)


Legend

In a step's parts box, this drop beside a screw's quantity means:
put threadlocker (blue 243) on the screw's thread before it goes in.


1 The control box




1




1×
OSSM board




1×
PCB box






2




2× M3×8 Screw

2.5 mm Hex key





3




1×

PCB lid






4



4× M3×8 Screw

2.5 mm Hex key




5




1×


Motor wiring harness




6




7




2 mm
Flat screwdriver




8




9




2 mm
Flat screwdriver




2 On the stand




10




11






12




2× M6×12 Screw


5 mm Hex key




13




14



15




16





1×

24V
power supply



17





You may now plug the power supply into the wall.

RESEARCH + DESIRE

OSSM Wiring Guide

V2.3 Board - V1.0.9

Support

support@researchanddesire.com

Assembly instructions

ohai.researchanddesire.com/ossm