
OSSM

Wired Remote Guide

Remote V2 - V1.0.8

RESEARCH + DESIRE




Support
support@researchanddesire.com

Assembly instructions
ohai.researchanddesire.com/ossm

Parts

Electronics




1×
Remote board




1×
Ethernet cable

3D printed



1×
Body



1×
Top cover



2×
Knob

Hardware



8 mm
2×
M4×8
Button head screw

Actual size



Print at 100 % (actual size). Lay a part on its dashed outline to identify it.

Bolts



M4×8 Button head screw

Hex keys



2.5 mm Hex key


Tools

Required




2.5 mm
Hex key


1 Fully built wired remote




1




1×
Remote board



1×
Body




2



1×

Top cover



3




2×

M4×8
Button head screw




2.5 mm Hex key



4



2×
Knob



2 The cable




5





1×

Ethernet cable



6





Turn the left knob to OFF, then plug the power supply into the wall.

RESEARCH + DESIRE

OSSM Wired Remote Guide

Remote V2 - V1.0.8

Support
support@researchanddesire.com

Assembly instructions
ohai.researchanddesire.com/ossm