


Condition of Second Internal Road from Vashi Village Entrance Arch (i.e Second Parallel Road to the Senior Citizens' Park situated opposite to Odisha Bhawan & Kerala House)



Ref: Representation made to The Commissioner, NMMC, Navi Mumbai with CC to Ward Officer, C-Ward office-Vashi & Hon'ble Corporator, Ward 65, Vashi Gaon (NMMC Ref: Sr. No: 2941 dt 15/4/2025)

Encls: Representation submitted on 15/4/2025 along with the photos of the road.

Representation from Residents of the Co-operative Housing Societies residing on both sides of the road

Vashi Gaon

Date: 15 / 4 2025

From,

The Residents,
Vashi Gaon (GES)
Sector - 31, Vashi
Navi Mumbai - 400703

आवक क्र. 2941

To,

The Commissioner,
NAVI MUMBAI MUNICIPAL CORPORATION
Ground Floor, Sector-15 A,
Palm Beach Junction, CBD Belapur,
Navi Mumbai,
Maharashtra-400614

m. p. Jodho ① दस्त
लेखनिक 15/4/25
नवी मुंबई महानगरपालिका

Respected Sir,

Sub: Request for Cement Concreting (CC) of internal Road - Plea from residents.

We are very much thankful to you for upgrading the sewer lines in our area, replacing the very old lines with bigger lines and manholes, and also for modernising the underground pipelines on war footing when there was a sudden burst some time ago. We also appreciate the health awareness drive NMMC is implementing though door to door visit by medical staff and the city beautification efforts. We feel proud of being residents of a well-planned city under your administration supported by dedicated and sincere NMMC Staff, Ward Office and our Esteemed Area Corporator.

We take this opportunity to bring to your kind attention that the second road from the arch (opposite to Kerala House) to the entrance of the village, where we reside on both sides of the road, is very uneven causing tipping over of children and adults. We also have several super senior citizens using the uneven road and the falls can be even more dangerous to them. The road has been accumulating a lot of runoff water forming puddles during rainy season causing a lot of difficulty to walk and school going children are affected a lot getting their uniforms soiled. It is also collecting a lot of dust in the pits making the entire area dirty.

Hence, we collectively request you to kindly take necessary action for getting the damaged bitumen road replaced with cement concrete road as early as possible to overcome the difficulties being faced by us.

Page 1 of 2









P/c

लिपिक
सी-विभाग वाशी
नवी मुंबई महानगरपालिका

Thanking you and looking forward for your kind support.

Yours sincerely,

Area residents of Co-operative Housing Societies.


S. No	Plot No (s)	Name of the CHS	Represented by with Tel No	Signature
1.	361 & 362	Vighnagar CHS	Nilesh Indulkar (Secretary) 7506187588	
2.	392 & 403	Satavahana CHS	T.S. Hari (Chairman) 9820492608	
3.	360 A	Ravi Kalpa	Vishal Kotkar 8879178146	
4.	360	Gourinandan CHS	Hira Vira Waghela 9136303796	
4.	411	Shree Datt CHS	Kishor Singh (Secretary) 9820979826	
5.	390 & 391	(Late) Lilawatibai Bachchu Bhagat Niwas	Baliram Bhagat 8691905353	
6.	393 & 402	Jamnotri CHS	Subhash Khandelot (Chairman) 7738405464	
7.	379	Ichhapuri Building	Ajit D. Vishve 9869055009	
8.	381	Samarth Nivas CHS	Sunil Pund 9322518251	
9.	382	Rama Apts	P. Venu Babu 9920219522	
10.	378	Shiv Parvathi	Vasudeo C. Patil 8097606446	
11.	363 & 364	Karmakar House	Ramesh Karmakar 9820720608	
12.	365 & 366	Mai Kalyaan	Menon 9321085885	
13.	379 A	Enkay Residency	Tabrez A. Shaikh 9819577179	

Copies circulated for kind information and follow up:

1. The Ward Officer

6th Floor – "C-Ward Office-Vashi", Plot No 1, Sector 16A,
New Ward Office, NMMC, VASHI, Navi Mumbai – 400703.

2. Smt. Fashibai K. Bhagat, Honourable Corporator, Ward 65,
Vashi Gaon, Sector 31, Vashi, Navi Mumbai – 400 703


श्रीमती. फाशिबाई करसन भागत
नगरसेविका, वार्ड 65, नवी मुंबई
15/11/25

West End of the road



Severely Damaged Road and Drain Area







Severely Eroded road and Speed Breaker
Can't be visualised















Permanent water stagnation during peak rainy season



