

0,5,5
0,5,0
0,-5,5
0,-5,0
0,0,2.5
4,5,5
4,5,0
4,-5,5
4,-5,0
4,0,2.5
8,5,5
8,5,0
8,-5,5
8,-5,0
8,0,2.5
12,5,5
12,5,0
12,-5,5
12,-5,0
12,0,2.5
16,5,5
16,5,0
16,-5,5
16,-5,0
16,0,2.5
20,5,5
20,5,0
20,-5,5
20,-5,0
20,0,2.5
24,5,5
24,5,0
24,-5,5
24,-5,0
24,0,2.5
28,5,5
28,5,0
28,-5,5
28,-5,0
28,0,2.5
32,5,5

32,5,0
32,-5,5
32,-5,0
32,0,2.5
36,5,5
36,5,0
36,-5,5
36,-5,0
36,0,2.5