## بسمه تعالی فرمولهای میان ترم درس فیزیک الکترونیک دکتر رحیمی



$$E = h\nu$$

$$n_{0} = N_{c}e^{-(E_{c}-E_{f})/K_{B}T}$$

$$N_{c} = 2\left[\frac{2\pi m_{n}^{\star}K_{B}T}{h^{2}}\right]^{\frac{3}{2}}$$

$$n_{i} = \sqrt{N_{c}N_{v}}e^{-E_{g}/K_{B}T}$$

$$n_{0} = n_{i}e^{(E_{f}-E_{i})/K_{B}T}$$

$$\mu = \frac{v}{\varepsilon}$$

$$\mu = q\frac{\tau}{m}$$

$$\frac{D}{\mu} = \frac{K_{B}T}{q}$$

$$J_{n} = nq\mu_{n}\varepsilon + qD_{n}\frac{\partial n}{\partial x}$$

$$g_{th} = \alpha_{r}n_{0}p_{0}$$

$$g = g_{th} + g_{opt}$$

$$\frac{dn}{dt} = \frac{\partial n}{\partial t} - \frac{1}{q}\frac{\partial}{\partial x}J_{n}$$

$$n = n_{i}e^{(F_{n}-E_{i})/K_{B}T}$$

$$Si : E_{g} = 1.11eV, n_{i} = 1.5 \times 10^{10}cm^{-3}$$

$$GaAs : E_{g} = 1.43eV, n_{i} = 10^{6}cm^{-3}, \epsilon_{r} = 13.2$$

$$m^* = \frac{\hbar^2}{\frac{\partial^2 E}{\partial k^2}}$$

$$p_0 = N_v e^{-(E_f - E_v)/K_B T}$$

$$N_v = 2 \left[ \frac{2\pi m_p^* K_B T}{h^2} \right]^{\frac{3}{2}}$$

$$E_i = \frac{(E_c + E_v)}{2} + \frac{3}{4} K_B T \ln\left(\frac{m_p^*}{m_n^*}\right)$$

$$p_0 = n_i e^{(E_i - E_f)/K_B T}$$

$$\sigma = \frac{J}{\varepsilon}$$

$$D = \frac{L^2}{2\tau}$$

$$I = I_0 e^{-\alpha t}$$

$$J_p = pq \mu_p \varepsilon - q D_p \frac{\partial p}{\partial x}$$

$$r = n.p$$

$$\tau = \frac{1}{\alpha_r (n_0 + p_0)}$$

$$\frac{dp}{dt} = \frac{\partial p}{\partial t} + \frac{1}{q} \frac{\partial}{\partial x} J_p$$

$$p = n_i e^{(E_i - F_p)/K_B T}$$

$$Si: m_n^* = 1.08 m_0, m_p^* = 0.56 m_0, \epsilon_r = 11.8$$