1/20	PT.PLN (Persero)
22	UIKL SULAWESI
PLN	UP2B Sistem Minahasa

FORMULIR FR.FAS.27

SCANNING ONLINE RELAY PROTEKSI SISTEM

Tupp

Merk	: SIEMENS	Lokasi	: GI OTAM
Туре	: Siprotek 75J82	Bay	: BBV TDI
No	: PIS 722 10	Ratio VT	: 20KV/100 V
Tanggal	: 13 APril 2023		/100 V

RELAY	WIRING
Setting UFR Island Enable	Standby Negative Trip di Selektor
☑ Cek Value Setting	Standby Positive Trip di Relay
Cek Measurment Tegangan	 Tarikan Rangkaian Trip Antar Panel
Cek Measurement Frekuensi	Posisi Aux Relay
Cek Time Relay	Periksa Terminal Rangkaian
Cek Ratio PT	Periksa Rangkaian Pada Relay
	Torrica rangitation and restay

fy: 48.75 Hz, f5: 48.65 Hz f6, f7 diso	12	11. CATATAN: f1: 49.2 HZ, f2: 49.05 Hz,
	ble	fy: 48.75 Hz, f5: 48.65 Hz
Penyulang attif So 1, SO2, SO3, SO 9		Penydang attif So 1, SO2, So

Mengetahui

Moch Hafid

Pemeriksa

Pengawas

Penauii

N

MARYO. H

Hendry E-