

FORMULIR FR.FAS.27

SCANNING ONLINE RELAY PROTEKSI SISTEM

Merk	: ALSTOM	Lokasi	: GI LOLAK
Туре	: 294 V	Bay	: BBVT TPI
No	:3785 6208/10/16	Ratio VT	: 20 ky/10 V
Tanggal	: 24 MEI 2023		/1(0 V

RELAY	WIRING	
Setting UFR Island Enable	Standby Negative Trip di Selektor	
Cek Value Setting	Standby Positive Trip di Relay	
Cek Measurment Tegangan	Tarikan Rangkaian Trip Antar Panel	
Cek Measurement Frekuensi	Posisi Aux Relay	
Cek Time Relay	Periksa Terminal Rangkaian	
Cek Ratio PT	Periksa Rangkaian Pada Relay	

III. CATATAN: The 1:49.2 Hz, Thez: 49.05 Hz, Thez: 48.9 Hz

The 4:48.75 Hz, The 5:40.65 Hz

Penyulang SLO 1,2,3,4 akfif samfai tahap 5

SLO 5,7 akfif samfai tahap 4.

SCO 4 tahap 2 Perbaiki Wiring, Skula lepas.

Mengetahui

Moch Hafid

Pemeriksa

Chiefinsa

HA TV

Penguji

ARYOH YUNAH

Perbaik, rangkaian antar patel 310 5 dan 510 7