| de | PT.PLN (Persero) | FORMULIR | SCANNING ONLINE RELA |
|-----|---------------------------------------|-----------|----------------------|
| PLN | UIKL SULAWESI UP2B Sistem Minahasa | FR.FAS.27 | PROTEKSI SISTEM |

upp

| Merk | : Schneider | Lokasi | : GI OTAM |
|---------|-----------------|----------|---------------|
| Туре | : MICOM P142 | Bay | : BBVT TD2 |
| No | :39623900/08/17 | Ratio VT | : 20 tV/100 V |
| Tanggal | :13 APML 2023 | | 7 (00 V |

| RELAY | WIRING | | |
|-----------------------------|------------------------------------|--|--|
| ✓ Setting UFR leland Enable | Standby Negative Trip di Selektor | | |
| Cek Value Setting | Standby Positive Trip di Relay | | |
| Cek Measurment Tegangan | Tarikan Rangkaian Trip Antar Panel | | |
| Cek Measurement Frekuensi | Posisi Aux Relay | | |
| Cek Time Relay | Periksa Terminal Rangkaian | | |
| Cek Ratio PT | Periksa Rangkaian Pada Relay | | |
| | | | |

| CATATAN : _ | 11: | 49.2 | H2 | , -{ | 2: | 49.05 | -H2, | f3: | 48.9 | H2 |
|-------------|------|--------|----|------|----|-------|------------|-----|------|----|
| 2= | €3: | 48.75 | H2 | | | | # 0 | | | |
| Pencyu | lang | aicfif | 50 | 8 | | | | | | |

Mengetahui

Moch Hafid

Pemeriksa

Pengawas

Penguji

Hendry