

FR.FAS.27

SCANNING ONLINE RELAY PROTEKSI SISTEM

Merk

: SIEMENS

Lokasi

: GI TILAMUTA

Туре

: Argus 7SR2204

Bay

: BBVT

No

: 3F1901506300

Ratio VT

: 20000 V/100 V

Tanggal

: 10 MEI 2023

I. CHECK LIST	a .		
RELAY	WIRING		
Setting UFR taland Enable	Standby Negative Trip di Selektor		
☑ Cek Value Setting	Standby Positive Trip di Relay		
Cek Measurment Tegangan	Tarikan Rangkaian Trip Antar Panel		
Cek Measurement Frekuensi	Posisi Aux Relay		
☐ Cek Time Relay	Periksa Terminal Rangkaian		
Cek Ratio PT	Periksa Rangkaian Pada Relay		

II. CATATAN :	Tahap	1:49.2 Hz	DO5	* Pengulary Artif / operasi
	Tahap	2:49.05 Hz	D06	TA1, TA3, TA4
Dog	Tahap	3: 48.9 Hz		* Penambahan / aktipa: stage 1-5
POZ Tahap \$4: 48.75 Hz		Pd Relay UFR Siemens		
008	Tohay	5 : 40-65	H2	

Mengetahui

Pemeriksa

Pengawas

Penguji

Moch Hafid

Rudi Yanto

Maryo Harly

Annisa Elma