
Figure 3-1 Correlatogram for TSS indicators



X = non-significant at p < 0.05 (Adjustment: Holm)

X = non-significant at p < 0.05 (Adjustment: Holm)