
Forecast responds smoothly to Ma
rms change of forecast
0.6
0.4
0.2
0.0
true Ma
0.5
0.6
0.7
0.8
0.9
Mach number given to the model