Orbit T2 Troubleshooting Guide

Lumen Home is a fictional company. Sample data for the MultiSource RAG Chatbot.

Error codes

E-114 Low power. The thermostat is not getting continuous power.
Install the C-wire adapter or connect a C-wire. Random reboots are a sign.

E-207 Wi-Fi connection failed. Check the password and that the router is on.
Move the router closer or use the 2.4 GHz band, which reaches further.

E-310 Temperature sensor fault. Restart the thermostat from Settings > Restart.
If the error returns within a day, contact Lumen Home support.

E-402 No heating detected. The system did not heat within 15 minutes.
Check the furnace switch, the breaker and the W1 wire.

E-405 No cooling detected. The system did not cool within 15 minutes.
Check the outdoor unit breaker and the Y1 wire.

Common problems

The display is blank: check the breaker, then make sure the display is clipped firmly onto the base plate. Wait two minutes after power returns.

The room feels warmer than the setting: the thermostat may be in direct sunlight or above a lamp. Move it, or add a wireless room sensor and set it as primary.

The schedule is ignored: check that Hold is not active. A manual change holds until the next schedule step unless you choose Hold permanently.

Contacting support

Have your serial number ready. It is in Settings > About and on the box. Support hours are 8 a.m. to 8 p.m., Monday to Saturday.