

Deviation / Incident Report

Report Date: 2026-09-24
Reported By: John Doe, Quality Assurance

1. Basic Information

Site / Plant: API Manufacturing Unit
Date of Occurrence: 2026-09-23
Source of Deviation: Quality Control (QC)
Related Product / Material: Metformin Hydrochloride API
Batch / Lot Number: MFH-2609-042

2. Deviation Details

Description of Event:

During routine QC testing of Batch MFH-2609-042, an Out-of-Specification (OOS) result was observed for the Assay parameter. The result obtained was 96.5%, which is below the lower limit of 98.0%. The analysis was repeated by a second analyst using the same sample preparation, and a result of 96.7% was obtained, confirming the initial OOS finding.

Immediate actions taken:

The batch has been quarantined, and a hold label was applied. The production team has been notified to halt any further processing or packaging of the related intermediate batches until the root cause is identified.

3. Initial Assessment

Initial Impact Assessment: The impact is expected to be High as this concerns the primary active ingredient and fails the critical Assay specification, meaning the batch cannot be released.

Initial Severity: Critical