Req.	Pseudorandom			Model checking TA			BDI agents		
	Р	F	NC	Р	F	NC	P	F	NC
Cooperative Manufacturing Assistant (160 tests per method)									
1	19	4	137	37	50	73	45	16	99
2	3	0	157	35	10	115	31	5	124
3	24	0	136	97	0	63	63	2	95
4	57	0	103	99	0	61	72	0	88
5	33	31	96	128	2	30	79	4	77
6	160	0	0	160	0	0	160	0	0
Home Care Assistant (50 tests per method)									
1	16	7	27	19	11	20	17	6	27
2	19	7	24	13	16	21	21	7	22
3	38	11	1	29	19	2	40	8	2
4	13	36	1	2	46	2	10	38	2