



INVOICE DATE	INVOICE NO.
7-27-26	1005889

Ditch Witch® West, A Papé Company, PO Box 987, Eugene, OR 97440

SERVICE INVOICE

This sale is subject to Papé's Terms and Conditions of Sale effective on the date hereof, which are incorporated in full by this reference. The Terms and Conditions of Sale are available at www.pape.com/terms, and will also be sent by mail or e-mail to the purchaser upon request.

NORTH SKY COMM NON-CMW
NON-CMW & WORK ORDER
16701 SE MCGILLIVRAY BLV
VANCOUVER WA 98683

0102
1

S
H
I
P
T
O
NORTH SKY COMM. NON-CMW
10860 SW CLUTTER STREET
SHERWOOD OR 97140

PHONE: 360-254-6920

CUSTOMER NO.	TYPE	DATE OPENED	PURCHASE ORDER NO.	AUTHORIZED BY / RELEASE NO.	
13973	CHARGE	7-14-26	73520		
MAKE	MODEL	SERIAL NO.		EQUIP NO.	METER
DW	HX30	DWPXH30XAN0001540		73520	1628
QUANTITY	DESCRIPTION			EACH	AMOUNT
SEGMENT 001					
LUCAS WAHTO 971-301-3969					
CALL CUSTOMER FOR ISSUES AT HAND.					
TECH 19087					
FIELD SERVICE CALL REQUESTED FOR REAR DOOR NOT LOWERING.					
UPON ARRIVAL, TESTED THE SWITCH FUNCTION AND CONFIRMED THE					
HYDRAULIC DOOR WOULD RAISE BUT WOULD NOT LOWER. PERFORMED					
ELECTRICAL DIAGNOSTICS AND MEASURED SWITCH RESISTANCE,					
FINDING 4.2 OHMS (UP) AND 4.3 OHMS (DOWN), BOTH WITHIN THE					
SPECIFIED 3 5 OHM RANGE. CHECKED CONTINUITY AND RESISTANCE					
OF THE SWITCH HARNESS TO THE VALVE BODY HARNESS AND FOUND					
ALL WIRING TESTED GOOD WITH NO OPEN OR SHORTED CIRCUITS.					
CLEANED THE SWITCH CONTACTS AND REPLACED THE SWITCH WITH A					
NEW ONE, BUT THE CONCERN REMAINED. CONTINUED DIAGNOSTICS AT					
THE HYDRAULIC VALVE ASSEMBLY, CLEANED CORROSION FROM THE					
SOLENOID VALVE CONNECTIONS, AND FOUND A DAMAGED TERMINAL PIN					
ON WIRE 22 AT THE VALVE BODY-TO-SWITCH CONNECTOR. REPAIRED					
THE TERMINAL, REASSEMBLED THE CONNECTOR, AND RETESTED THE					
SYSTEM. VERIFIED THE REAR DOOR NOW RAISES AND LOWERS					
PROPERLY WITH NO FURTHER ISSUES. ALL OPERATIONS ARE WORKING					
AS DESIGNED AT THIS TIME.					
PARTS		LABOR			
.00		562.50		TIME/MATERIALS	562.50
.00		2.87		OR CAT REC - SERV	2.87
SEGMENT TOTAL-->					565.37
SEGMENT 002					
TRAVEL TIME AND MILEAGE.					
SERVICE SUPPLIES					22.06
ENVIRONMNTL SERVICES					40.00
MILEAGE					37.50
Payment should be by cash, check or ACH/wire transfer				DESCRIPTION	AMOUNT
SUBMIT PAYMENTS ONLY TO: Ditch Witch West PO Box 35144 #5077 Seattle, WA 98124-5144				TOTAL PARTS	
				TOTAL LABOR	
www.ditchwitchwest.com				PLEASE PAY THIS TOTAL >	CONTINUED



Ditch Witch[®]
West

INVOICE DATE

7-27-26

INVOICE NO.

1005889

Ditch Witch® West, A Papé Company, PO Box 987, Eugene, OR 97440

SERVICE INVOICE

This sale is subject to Papé's Terms and Conditions of Sale effective on the date hereof, which are incorporated in full by this reference. The Terms and Conditions of Sale are available at www.pape.com/terms, and will also be sent by mail or e-mail to the purchaser upon request.

NORTH SKY COMM NON-CMW
NON-CMW & WORK ORDER
16701 SE MCGILLIVRAY BLV
VANCOUVER WA 98683

0102
2

S
H
I
P
T
O

NORTH SKY COMM. NON-CMW
10860 SW CLUTTER STREET

PHONE: 360-254-6920 SHERWOOD OR 97140

CUSTOMER NO.		TYPE	DATE OPENED	PURCHASE ORDER NO.	AUTHORIZED BY / RELEASE NO.	
13973		CHARGE	7-14-26	73520		
MAKE	MODEL	SERIAL NO.		EQUIP NO.	METER	
DW	HX30	DWPXH30XAN0001540		73520	1628	
QUANTITY	DESCRIPTION			EACH	AMOUNT	
SEGMENT 002 CONTINUED						
PARTS	LABOR		TIME/MATERIALS		332.06	
99.56	232.50		OR CAT REC - SERV		1.69	
.50	1.19		SEGMENT TOTAL-->		333.75	