



MACHINERY

Papé Machinery, Inc., PO Box 10527, Eugene, OR 97440

INVOICE DATE

7-27-26

INVOICE NO.

7011328



JOHN DEERE

SERVICE INVOICE

This sale is subject to Papé's Terms and Conditions of Sale effective on the date hereof, which are incorporated in full by this reference. The Terms and Conditions of Sale are available at www.pape.com/terms, and will also be sent by mail or e-mail to the purchaser upon request.

NORTHSKY COMMUNICATIONS	7001	SHIP TO	NORTHSKY COMMUNICATIONS
16701 SE MCGILLIVRAY BL	1		16701 SE MCGILLIVRAY BL
SUITE 200			SUITE 200
VANCOUVER			VANCOUVER
WA 98683	PHONE: 800-755-6920		WA 98683

CUSTOMER NO.	TYPE	DATE OPENED	PURCHASE ORDER NO.	AUTHORIZED BY / RELEASE NO.
6107928	CHARGE	6-24-26	73953 JOSH	M70-014612
MAKE	MODEL	SERIAL NO.	EQUIP NO.	METER
JD	310SL	1T0310SL LJF336477		2787
QUANTITY	DESCRIPTION		EACH	AMOUNT
SEGMENT 001				
(KH) DIAGNOSE LOADER BUCKET NOT CURLING				
CAUSE: BUCKET WOULDNT CURL FOUND WHEN RAISING THE BUCKET				
THAT IT WOULD CURL SLOWLY				
CORRECTION: THE FLOOR MAT AND FLOOR BOARD WERE REMOVED TO				
ACCESS THE LOADER LEVER, BUT VISIBILITY WAS STILL LIMITED.				
THE COVER FROM THE LOADER LEVER WAS REMOVED, YET ACCESS TO				
THE LINKAGE REMAINED DIFFICULT. THE RIGHT REAR TIRE WAS				
THEN STARTED TO BE REMOVED, BUT THE INCH DRIVE COULD NOT				
LOOSEN THE LUG NUTS. LES SCHWAB WAS CONTACTED, AND THEY				
ASSISTED IN REMOVING THE LUG NUTS. ONCE THE WHEEL AND THE				
COVER BEHIND THE WHEEL WERE REMOVED, A PIECE OF GRAVEL WAS				
FOUND UNDER THE LINKAGE. THE GRAVEL WAS KNOCKED OUT, AND				
THE BUCKET NOW CURLS PROPERLY. THE WHEEL COVER, FLOOR				
BOARD, AND FLOOR MAT WERE REINSTALLED.				
FAILURE MODE: OUT OF ADJUSTMENT				
FAILURE AREA: 070 - HYDRAULICS				
PARTS		LABOR		
.00		594.00	TIME/MATERIALS	594.00
.00		52.87	STATE/LOCAL TAX	52.87
			SEGMENT TOTAL-->	646.87
SEGMENT 099				
TRAVEL TIME AND MILEAGE				
SERVICE SUPPLIES				40.87
SERVICE TRIP				.00
PARTS		LABOR		
40.87		223.30	TIME/MATERIALS	264.17
3.64		19.87	STATE/LOCAL TAX	23.51
			SEGMENT TOTAL-->	287.68
Payment should be by cash, check or ACH/wire transfer			DESCRIPTION	AMOUNT
FOR ALL YOUR CONSTRUCTION		SUBMIT PAYMENTS ONLY TO: Papé Machinery PO Box 35144 #5077 Seattle, WA 98124-5144	TOTAL PARTS	40.87
AND FORESTRY NEEDS CALL:			TOTAL LABOR	817.30
PAPÉ MACHINERY			SPECIAL SERVICES	
SPOKANE, WA			STATE/LOCAL TAX	76.38
(509) 838-5252			PLEASE PAY >	934.55
			THIS TOTAL >	
TERMS: PAYMENT DUE 08/06/26				
www.papemachinery.com				