



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	01
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181	D10x15S3VP	2226	1VRA130VLP1003083	05/25/25
	D10X15III			1000 B

** Buy parts online and view your invoices at RDOequipment.com/account.

SEGMENT# 1 C RNM01 0000 10/16/25 10/17/25

Diagnostic

CONDITION:

Leak from mud pump and leak from water shut off valve

REPAIR:

10-17-25 RM

- arrived to job site
- removed cover to gain access to water shut off valve
- had customer run drill
- found mud leaking from water shut off valve
- new segment started for repair

10-17-25 RM

- found oil leaking from mud pump drive coupler area
- checked mud pump oil level (good)
- removed mud pump drive motor from mud pump
- had customer run drill while inspecting mud pump drive motor shaft for leaks
- found mud pump drive motor leaking from shaft seal
- new segment started and parts ordered for repair
- reinstalled motor until new motor arrives

ADDITIONAL DESCRIPTION:

Vermeer Standard (WARR VERMEER)
Causal Part:296431402,296308170
Diagnostic Hours:

10401099 10501077

LABOR	307.20
SEGMENT TOTAL==>	307.20
CONTINUED ON PAGE 02	

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	02
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181 D10x15S3VP	2226	1VRA130VLP1003083	05/25/25	1000 B
D10X15III				

SEGMENT# 2 C RNM01 A003 10/16/25 10/17/25

Travel Time

REPAIR:

10-17-25 RM

- travel to job site
- travel to hydraulic for hose build
- travel back to job site
- travel to Portland Shop

ADDITIONAL DESCRIPTION:

Vermeer Travel

Travel From: 7640 NE 33rd DR Portland Oregon

Repair Location:1810 SE Park Crest Ave

Roundtrip Mileage:25

1. Travel Time (A003)

Quantity

HRS
0.00
=====
x1
=====
0.00

10401099 10501077

LABOR	483.80
SEGMENT TOTAL==>	483.80

SEGMENT# 3 C RNM01 9023 10/16/25 10/16/25

Water Shutoff Valve Seal Kit R&R CMP

CONDITION:

remove and replace water shut off valve

DIAGNOSTICS:

internal failure

REPAIR:

CONTINUED ON PAGE 03

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	03
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181 D10x15S3VP	2226	1VRA130VLP1003083	05/25/25	1000 B
D10X15III				

10-17-25 RM

- removed water hoses going into shut off valve
- removed water shut off cylinder from valve
- removed valve from machine
- transferred fittings to new valve (replaced o-rings)
- installed shut off valve in reverse order
- confirmed valve opens and closes as it should
- could NOT test for leaks as water was not hooked up
- customer states they will check later this afternoon

ADDITIONAL DESCRIPTION:

Vermeer Standard (WARR VERMEER)

Causal Part:296431402

Diagnostic Hours:

296431402	VALVE-2 WAY BAL	1	162.06	162.06
			PARTS	162.06
			LABOR	166.05
10401099 10501077			SEGMENT TOTAL==>	328.11

SEGMENT# 4 C DK001 9020 10/16/25 10/16/25

Mud/Water Pump Drive Motor R&R CMP

CONDITION:

removed and replace mud pump drive motor

DIAGNOSTICS:

shaft seal leaking

REPAIR:

10-17-25 RM

-ordered new drive motor RED

07-24-26 - DK

- Machine moved into shop, pix uploaded to multimedia.

CONTINUED ON PAGE 04

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	04
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181	D10x15S3VP	2226	1VRA130VLP1003083	05/25/25
	D10X15III			1000 B

- Guards removed from around existing hyd. motor.
- Hyd. lines disconnected and capped.
- Failed hyd. motor removed from machine.
- Mounting area cleaned up.
- Fittings transferred to new motor with all new o-rings.
- New hyd. motor installed and hyd.lines reconnected.
- Pix of data tags for both hydraulic motors added to multimedia.
- Failed motor tagged and placed in warranty area.
- SEGMENT COMPLETE.

ADDITIONAL DESCRIPTION:

Vermeer Standard (WARR VERMEER)

Causal Part:296308170

Diagnostic Hours:

Pix of old and new motor data tags in multimedia

FRT	SHIP/HANDLING	1	Warr/Int	Warr/Int
296308170	MOTOR - 3. 0 CI	1 N	Warr/Int	Warr/Int
	PARTS		Warr/Int	
	LABOR		Warr/Int	
10401099 10501077 74304477	SEGMENT TOTAL==>		Warr/Int	

SEGMENT# 5 C RNM01 4200 10/16/25 10/17/25
Hydraulic Hose (each) R&R (only)

CONDITION:

remove and replace hydraulic hose near water shut off valve

DIAGNOSTICS:

leaking from crimp

REPAIR:

10-17-25 RM

-removed cover to gain access to water shut off valve and

CONTINUED ON PAGE 05

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	05
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181 D10x15S3VP D10X15III	2226	1VRA130VLP1003083	05/25/25	1000 B
cylinder removed hydraulic hose for water shut off cylinder -removed and replaced fitting o-ring -installed hose in reverse order -marked hose with red paint pen -function tested machine -machine running as it should -no leaks found				
HE568-908-90DV	08 viton oring	10	.76	7.60
HE568-912-90DV	12 viton oring	10	1.76	17.60
HE568-914-90DV	14 viton oring	5	1.48	7.40
ROCK/2SN-06-M03400-04	HYDRO HOSE	1	58.42	58.42
			PARTS	91.02
			LABOR	102.50
10401099 10501077			SEGMENT TOTAL==>	193.52

SEGMENT# 6 C DK001 SB25-045 10/16/25 07/24/26
SVC2025-045 Loop Flush Manifold Upgrade

CONDITION:

IK Install

DIAGNOSTICS:

N/A

REPAIR:

07-24-26 - DK

- Moved machine into the shop and staged it for repairs.
- Removed necessary hoses as per IK instructions.
- Replaced hoses as per IK instructions.
- Replaced manifold block.
- Replaced hardlines on thrust motors.
- Topped off hydraulic oil level.

CONTINUED ON PAGE 06

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	06
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181	D10x15S3VP	2226	1VRA130VLP1003083	05/25/25
	D10X15III			1000 B

- Function tested machine - NO IDSSUES WITH IK INSTALL
- SEGMENT COMPLETE.

ADDITIONAL DESCRIPTION:

- | | |
|--|------|
| 1. SVC2025-045 Loop Flush Manifold Upgrade
(SB25-045) | HRS |
| Ensure the machine is turned off and disconnected from
any p | 2.00 |
| Remove any covers or guards obstructing access to the
loop f | |
| Disconnect any hydraulic lines and electrical
connections at | |
| Loosen and remove the bolts securing the manifold.
Carefully remove the manifold from its housing.
Position the new manifold in place.
Secure it with the bolts you previously removed,
tightening | |
| Reconnect the hydraulic lines and electrical
connections. | |
| Reattach any covers or guards you removed.
Reconnect the machine to its power source.
Perform a test run to ensure the new manifold is
functioning | |

Quantity

=====
x1
=====
2.00

10501077 74304477

LABOR Warr/Int
SEGMENT TOTAL==> Warr/Int

CONTINUED ON PAGE 07

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	07
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
Z145181 D10x15S3VP	2226	1VRA130VLP1003083	05/25/25	1000 B
D10X15III				

SEGMENT# 7 C RNM01 1016 10/16/25 10/17/25

RH Joystick Controller R&R

CONDITION:

right hand joystick failure

DIAGNOSTICS:

failed right hand joystick

REPAIR:

7-25-26 RM

-removed right hand joystick

(one mounting bolt sheared off and 2 missing)

-installed new in reverse order

-function tested machine

-machine operating as it should

ADDITIONAL DESCRIPTION:

1. Diagnostic (0000)

Quantity

HRS
1.50
=====
x1
=====
1.50

296584042	JOYSTICK - DUAL	1	1874.59	1874.59
			PARTS	1874.59
			LABOR	231.65
10401099	74304477		SEGMENT TOTAL==>	2106.24

***** WORK ORDER TOTALS *****
INTERNAL CUSTOMER
PARTS Warr/Int 2127.67
CONTINUED ON PAGE 08

Thank you for your business



RDO Equipment Co.
7640 NE 33rd Drive
Portland, OR 97211
503-282-0694
Fax: 503-281-8601

For Billing Inquiries or to
receive invoices via E-mail or
MyDealer website, please contact
RDOAR@rdoequipment.com

Ship to: N/A

Invoice to: NORTH SKY COMMUNICATIONS, INC.
16701 SE MCGILLIVRAY BLVD
STE 200
VANCOUVER WA 98683

Branch
PORTLAND, OR

Date	07/30/26	Time	21:18:02 (B)	Page	08
Account No.	6692001	Phone No.	3602546920	Invoice No.	W3060577
Ship Via		Purchase Order	73923/JOSHH		
Tax Exemption Number		Federal ID Number			
		Salesperson	GF8		

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS	
Z145181	D10x15S3VP	2226	1VRA130VLP1003083	05/25/25	1000 B
	D10X15III				
			LABOR	Warr/Int	1291.20
			INTERNAL TOTAL	Warr/Int	
			TOTAL DUE RDO		3418.87

+-----+
| Payments are due on your RDO account 30 days from the invoice date |
+-----+

PLEASE REMIT TO: RDO EQUIPMENT CO.
1707 EAST JAMES ST.
PASCO, WA 99301-5936

Thank you for your business