



Account#	Work Ord	Br	Sls
7991	81002824	081	VMW

W O R K O R D E R
I N V O I C E

Date	Invoice #	Page
08-25-25	08117647	1

Sold To: 000 Ship To:
NORTH SKY COMMUNICATIONS NORTH SKY COMMUNICATIONS
16701 SE MCGILLIVRAY BLVD STE 200 16701 SE MCGILLIVRAY BLVD STE 200
VANCOUVER WA 98683 VANCOUVER WA 98683

Ship Via: WILL CALL

Purchase order	Date	Job Number	Job Contact
	08-21-25		

Seg# 001 Mfr:VER Model:PTX44 S/N:1VR8072S3H1000297 Meter: 919
Equip ID:PTX44-00297

Diagnostic

DIAGNOSTIC - FULL GO THROUGH

*ECU FAULT (LOWER POWER & SMOKING)
*BOG DOWN & BLACK SMOKE
INTERMITTENT & HARD TO START
*106.40 IS THE CODE
FLAT TIRE

TACH NOTES:

NEEDS FUEL PRESSURE MANIFOLD
FIXED CODES

MAP SENSOR WAS UNPLUGGED & FUEL PRESSURE MANIFOLD IS FAULTY

Total Labor	180.00
Total for segment	180.00

Seg# 002 Mfr:VER Model:PTX44 S/N:1VR8072S3H1000297 Meter: 919
Equip ID:PTX44-00297

Engine

FUEL PRESSURE MANIFOLD

SIGNATURE/FIRMA _____

Continued

WE APPRECIATE YOUR BUSINESS!

For Terms and Conditions, go to

<https://vermeermountainwest.com/terms-conditions/>

FOR ADDITIONAL TERMS AND CONDITIONS: <https://vermeermountainwest.com/terms-conditions/>



Account#	Work Ord	Br	Sls
7991	81002824	081	VMW

W O R K O R D E R
I N V O I C E

Date	Invoice #	Page
08-25-25	08117647	2

Sold To: 000 Ship To:
NORTH SKY COMMUNICATIONS NORTH SKY COMMUNICATIONS
16701 SE MCGILLIVRAY BLVD STE 200 16701 SE MCGILLIVRAY BLVD STE 200
VANCOUVER WA 98683 VANCOUVER WA 98683

Ship Via: WILL CALL

Purchase order	Date	Job Number	Job Contact
	08-21-25		

Ensure the machine is turned off and the key is removed. Allow the engine to cool down before starting any work. Carefully relieve the fuel pressure in the system. This can usually be done by loosening the fuel cap or using a fuel pressure relief valve. Disconnect the fuel lines connected to the manifold. Be prepared for some fuel spillage and have a container ready to catch any fuel.

Unbolt the fuel pressure manifold from its mounting.

Position the new manifold and secure it with bolts. Ensure all gaskets and seals are properly placed to prevent leaks.

Attach the fuel lines to the new manifold. Make sure the connections are tight and secure.

Turn on the machine and check for any leaks. Ensure the fuel system is operating correctly.

1	296480630	MANIFOLD, FUEL P	1,139.22	1,139.22
1	EXPEDITED FREIGHT		33.01	33.01
		Total Labor		135.00
	Total for segment			1,307.23

ENVIRONMENTAL DISPOSAL FEE	15.00
-MISC SUPPLY	31.50

Total parts	1,139.22	Total labor	315.00	Total misc	79.51
				Sub Total	1,533.73
SALES TAX		SALES TAX			153.40

SIGNATURE/FIRMA _____

Amount Due
Due By:
09/24/25

1,687.13

WE APPRECIATE YOUR BUSINESS!

For Terms and Conditions, go to

<https://vermeermountainwest.com/terms-conditions/>

FOR ADDITIONAL TERMS AND CONDITIONS: <https://vermeermountainwest.com/terms-conditions/>