

BAY COUNTIES DIESEL SERVICE INC.

Service Invoice 42705

Name	North Sky	Contact	Junior/ Kirk	Created Time	01/26/26	Year	2021
Address	16701 SE McGillvray Blvd Suite 200 Vancouver, Wa 98683	Address 2	5275 Central Ave. Fremont, Ca 94536	Invoiced	7:50 AM	Make	Ford
Home	Michel 971-412-8469	EstMiles		Advisor	01/30/26	Model	F550 Super Duty
Work	510-862-9946	V.I.N. #	1FDUF5GT5MDA01488	Division	Kevin	Lic#	YAS160
Fax	209-579-3495	Engine Dat		PO#	TR	Fleet#	72333
				Checked By		Body	
				Page#	1 of 2	Miles In	76,875
						Miles Out	76,875

Job Description

Perform B-PMI Service

Drain oil. Replace oil filter and fuel filter. Check drain plug and re-install. Fill to spec and check level. Remove and replace worn wiper blades as required. Cleaned and adjusted washer nozzles, filled with washer fluid to spec and checked function. Okay. Top off all fluid levels and check for leaks. Lube Chassis.

Part Number	Description	QTY	Each	Total
2703	Washer Fluid	1	5.75	5.75
31-22	Wiper Blades	2	10.52	21.04
DIESEL FUEL-	Fuel for Filter	1	9.88	9.88
EP NLGI 2	Ultra Duty Grease	1	8.89	8.89
FD4647	Fuel Filter Kit	1	160.48	160.48
LF17494	Lube	1	33.40	33.40
X010W30	10w30 OEM	13	27.80	361.40
Oil Disposal			3.90	3.90
Filter Disposal			1.60	1.60

Line Total	1000.34
2 Hours Labor	394.00
Parts	606.34
Sublets	0.00

Advise Right Front Wheel Stud Cross Threaded

Inspected unit and found right front wheel stud cross threaded. Raised axles and used lug nut extractor and heated up studs, used breaker bar and used grinder and cut off broken studs. Extract studs and cleaned threads. Installed new wheel studs and torque to spec.

Part Number	Description	QTY	Each	Total
610-619	SPACER STUD	3	24.28	72.84
611-931	WHEEL NUT	3	13.42	40.26
WS1	Welding Supplies	1	37.57	37.57

Line Total	721.97
2.9 Hours Labor	571.30
Parts	150.67
Sublets	0.00

Repair Brakes as Required

Performed visual inspection and found e-brakes worn and not operational when applied. Found front and rear brakes pads at wear limits. Found front and rear brake rotors worn to core. Found rear axle wheel seals leaking, advised customer recommend repairs.

Raised axles on lifts and removed wheels, brake calipers, brake pads and brake rotors. Removed axle shaft and hub assembly rear axle. Removed leaking wheel seal and steam cleaned brake hubs. Installed new wheel seals and greased bearings to spec. Installed new brake rotors and brake pads,

Line Total	3738.76
8.6 Hours Labor	1694.20
Parts	2044.56
Sublets	0.00

Bay Counties Diesel Service | 42370 Boyce Road, Fremont, CA 94538

Telephone 510-490-5665 | Fax 510-490-2572

All repairs performed by Bay Counties Diesel Service Inc. are warrantied for a period of 1 year. Warranty covers only work performed by Bay Counties Diesel Service, and does not cover any related parts or repairs. Bay Counties Diesel Service is not responsible for any external costs, including, but not limited to, towing, lodging, of loss of revenue or down time. Bay Counties Diesel Service owns the right to make all repairs under warranty internally. Any truck left over 15 days will be subject to a \$150.00 a day storage fee.

Invoice Total	
Labor	\$2,659.50
Parts	\$2,801.57
Sublets	\$0.00
Supplies	\$106.38
Subtotal	\$5,567.45
Tax	\$297.50
Total	\$5,864.95

BAY COUNTIES DIESEL SERVICE INC.

Service Invoice 42705

Name	North Sky	Contact	Junior/ Kirk	Created	01/26/26	Year	2021
Address	16701 SE McGillvray Blvd Suite 200 Vancouver, Wa 98683	Address 2	5275 Central Ave. Fremont, Ca 94536	Time	7:50 AM	Make	Ford
Home	Michel 971-412-8469	EstMiles	1FDUF5GT5MDA01488	Invoiced	01/30/26	Model	F550 Super Duty
Work	510-862-9946	V.I.N. #		Advisor	Kevin	Lic#	YAS160
Fax	209-579-3495	Engine Dat		Division	TR	Fleet#	72333
				PO#		Body	
				Checked By		Miles In	76,875
				Page#	2 of 2	Miles Out	76,875

Job Description

reinstalled wheels and fill with brake fluid to spec. Removed and replaced E-brake and made adjustments to linkage. Bled brake system and test drove unit. Checked brake function and checked for malfunctions. Okay

Part Number	Description	QTY	Each	Total
5C3Z-4A322-AA	SEAL RING	2	15.20	30.40
8C3Z-2648-B	E BRAKE SHOES KIT	1	103.54	103.54
F81Z*1001*BA	Seal,Outer Ring	2	8.51	17.02
HC3Z-1S175-C	WHEEL SEAL	2	76.73	153.46
HC3Z-2001-E	FRONT PADS	1	168.57	168.57
HC3Z-2200-E	REAR PAD KIT	1	176.55	176.55
PC3Z-1125-B	ROTOR ASSY	2	357.84	715.68
PC3Z-2C026-B	ROTOR	2	339.67	679.34

Date Service Due

04/27/2026 B-PMI

Bay Counties Diesel Service | 42370 Boyce Road, Fremont, CA 94538

Telephone 510-490-5665 | Fax 510-490-2572

All repairs performed by Bay Counties Diesel Service Inc. are warrantied for a period of 1 year. Warranty covers only work performed by Bay Counties Diesel Service, and does not cover any related parts or repairs. Bay Counties Diesel Service is not responsible for any external costs, including, but not limited to, towing, lodging, of loss of revenue or down time. Bay Counties Diesel Service owns the right to make all repairs under warranty internally. Any truck left over 15 days will be subject to a \$150.00 a day storage fee.

Invoice Total	
Labor	\$2,659.50
Parts	\$2,801.57
Sublets	\$0.00
Supplies	\$106.38
Subtotal	\$5,567.45
Tax	\$297.50
Total	\$5,864.95