

BAY COUNTIES DIESEL SERVICE INC.

Service Invoice 42887

Name	North Sky	Contact	Justin	Created	02/24/26	Year	2017
Address	16701 SE McGillvray Blvd Suite 200 Vancouver, Wa 98683	Address 2	5275 Central Ave. Fremont, Ca 94536	Time Invoiced	6:24 AM 03/10/2026	Make Model	Freightliner M2 106 Medium
Home Work Fax	Michel 971-412-8469 510-862-9946 209-579-3495	EstMiles	3ALHCYCY4HDHY8219	Advisor	Kevin	Lic#	29778H2-OREG
		V.I.N. #		Division	TR	Fleet#	42718
		Engine Dat		PO#	42718-Justin	Body	
				Checked By		Miles In	83,392
				Page#	1 of 1	Miles Out	83,392

Job Description

Check and Advise Engine De rate

Confirmed and verified engine de rate. Scanned ECM and checked for active faults. Confirmed active faults for turbo performance out of range and DEF level below spec and protection active. Followed diagnostic procedure. Tested battery voltage and checked for proper voltage supply from batteries to ECM and from ECM to DEF module and VGT assembly. Confirmed DEF level header unit of range. Checked VGT performance and confirmed failed. Advised customer recommend repairs.

Part Number	Description	QTY	Each	Total
	Computer Diagnostic Fee		99.00	99.00

Line Total	296.00
1 Hours Labor	197.00
Parts	99.00
Sublets	0.00

Install new DEF Level Header as Required

Removed tank strap brackets and lower DEF tank. Removed level sensors and cleaned connections. Installed new DEF header unit and tightened DEF tank strap brackets. Started engine and checked for leaks, Okay.

Part Number	Description	QTY	Each	Total
04-31354-001	DEF LEVEL HEADER	1	741.74	741.74
CV50628A	CRANKCASE FILTER	1	110.95	110.95

Line Total	1148.19
1.5 Hours Labor	295.50
Parts	852.69
Sublets	0.00

Install new VGT Assembly as Required

Confirmed and verified failed VGT assembly. Drain cooling system as required. Remove air intake system, electrical connections and sensors. Remove and replace VGT actuator and reassemble truck. Fill coolant and calibrate ECM. Test drove unit with scan tool connected to ECM. Check VGT parameters and check for active faults. Okay

Part Number	Description	QTY	Each	Total
6382091RX-1	REMAN VGT ASSY	1	1199.50	1199.50
AF26154	Air, Primary	1	136.65	136.65
Filter Disposal			0.80	0.80
Reflash ECM			550.00	550.00

Line Total	2477.95
3 Hours Labor	591.00
Parts	1886.95
Sublets	0.00

Bay Counties Diesel Service | 42370 Boyce Road, Fremont, CA 94538
Telephone 510-490-5665 | Fax 510-490-2572

All repairs performed by Bay Counties Diesel Service Inc. are warrantied for a period of 1 year. Warranty covers only work performed by Bay Counties Diesel Service, and does not cover any related parts or repairs. Bay Counties Diesel Service is not responsible for any external costs, including, but not limited to, towing, lodging, of loss of revenue or down time. Bay Counties Diesel Service owns the right to make all repairs under warranty internally. Any truck left over 15 days will be subject to a \$150.00 a day storage fee.

Invoice Total	
Labor	\$1,083.50
Parts	\$2,838.64
Sublets	\$0.00
Supplies	\$43.34
Subtotal	\$3,965.48
Tax	\$228.80
Total	\$4,194.28

Invoice Total	
Labor	- 3254.19
Sublets	
Supplies	\$940.09
Subtotal	
Tax	
Balance due now	

Invoice 42887 Balance = 940.09