

J.P. & FAMILY
ROADSIDE TRUCK REPAIR
Weed, CA
(530) 261-0550

JOB INVOICE

7531

BILL TO	North Sky	CUSTOMER ORDER #	DATE ORDERED
ADDRESS		ORDER TAKEN BY	DATE PROMISED
CITY	Called out to Fort Jones & No Start.	PHONE	TIME
JOB NAME AND LOCATION		MECHANIC	HELPER
DESCRIPTION OF WORK	Truck # 72688 Lic # YARZ768 miles 38264.7	☐ DAY WORK ☐ CONTRACT ☐ EXTRA	

QTY	DESCRIPTION OF MATERIAL USED	PRICE	AMOUNT
	Found 2 of the 3 Batteries shorted out. Installed 3 New Batteries. After that turned on Batt shut off + load Bang from Behind seat trailer control moved, on Hookel + terminal off + side of Batt. Then I got Power to Dash + Gauge's. Found Def tank Red light on. Then went to local Napa + Flued. Added Flued still No power to starter. Did Full Computer Diagnostic - Found 13 Different codes, checked And cleaned all + and - cables. Found 2 Bad Relays at Main Fuse Box - Returned to parts House For New Relays Returned to truck Replaced.		
11/15	Still No start at Key cleaned all code		
37	with Computer + Jumped starter at Sylmar. Runs 4-5 second + Dies.		

All Roadside repairs are temporary only.

HOURS	LABOR	AMOUNT	TOTAL MATERIALS	TOTAL LABOR	TOTAL
3	New Top Stub Batteries @ \$145 each.		515	00	
2	New Relays + clean spp's @ \$80		845	00	
	From shop + 2 trips 120 mile		210	00	
I hereby acknowledge the satisfactory completion of the above described work:			TAX	38	67
SIGNATURE			DATE COMPLETED	TOTAL	1608.67
			11/18/25		