GLOBAL WING FINANCE BV | AIRCRAFT LEASING

Global Wing Finance BV

RETURN CONDITION REPORT

Aircraft Return — Lease Expiry 2028-10-31

Reference: RCR-N67890-2028-10

Aircraft Type	MSN	Registration	Engines	Year
Airbus A319-100	**7203**	**N67890**	**CFM56-5B5/P**	**2016**

Role	Party	Jurisdiction
Lessor	Global Wing Finance BV	Ireland
Lessee	Coastal Charter Services Ltd.	USA
Return Location	Miami Intl Airport (MIA)	Florida, USA

FINAL — SIGNED

Dated: 2022-11-01

Coastal Charter Services Ltd.

This document is strictly confidential and is intended solely for the named parties. Any reproduction, disclosure, or distribution without the prior written consent of Global Wing Finance BV is strictly prohibited.

1. RETURN OVERVIEW

Parameter	Detail
Aircraft	Airbus A319-100 / N67890 / MSN 7203
Lease Expiry	2028-10-31
Return Date	2028-10-31
Return Location	Miami International Airport (MIA), FL, USA
Lessor Inspector	Declan Murphy (AME), Murphy Aviation Surveys Ltd
Lessee Inspector	James Parrish (A&P/IA), VP Engineering
Independent Inspector	AeroDynamic Advisory LLC
Total FH Accumulated (Lease Period)	15,363 FH
Total FC Accumulated (Lease Period)	11,611 FC

2. AIRFRAME STATUS AT RETURN

Parameter	At Delivery	At Return	Required	Status
Total FH	22,841	38,204	N/A	INFO
Total FC	16,203	27,814	N/A	INFO
FH since C-Check	4,102	2,218	Max 6,000 FH / 24 months	PASS
Date of last C-Check	2022-03-14	2029-11-08	Within 24 months	PASS
Open AD items	0	0	0 open	PASS
Open structural repairs	0	2	0 open	FAIL — compensation due
Open MEL items	3	5	Max Cat C in-window	FAIL — 2 items overdue

3. ENGINE STATUS AT RETURN

3. . Engine No. 1 — ESN ESN-334455

Parameter	Value	Required	Status
Date last PRSV	2027-08-15	Within 36 months	PASS
Months since last PRSV	29 months	Max 36 months	PASS
EGT Margin at Return	22°C	Min 30°C	FAIL — 8°C shortfall
Oil Consumption	0.28 qt/hr	Max 0.50 qt/hr	PASS
Vibration N1/N2	N1: 0.6 / N2: 0.5 IPS	Max 0.7 IPS each	PASS

3. . Engine No. 2 — ESN ESN-334456

Parameter	Value	Required	Status
Date last PRSV	2027-08-15	Within 36 months	PASS
Months since last PRSV	29 months	Max 36 months	PASS
EGT Margin at Return	22°C	Min 30°C	FAIL — 8°C shortfall
Oil Consumption	0.28 qt/hr	Max 0.50 qt/hr	PASS
Vibration N1/N2	N1: 0.6 / N2: 0.5 IPS	Max 0.7 IPS each	PASS

4. ENGINE LLP STATUS AT RETURN

LLPs below 2,500 FC remaining trigger compensation at USD 185/FC per LLP per lease Schedule 5.

Module	P/N	Desc	Life	CSN	Remaining	Shortfall FC	Compensation	Status
Fan	1794M90 P01	Fan Disk	30000	26433	3567	0	—	PASS
Fan	1794M91 P01	Fan Blade (set of 24)	20000	26433	0	2500	USD 462,500	FAIL
Fan	1794M92 P01	Fan Case	30000	26433	3567	0	—	PASS
LPC (Booster)	1795M10 P01	Booster Disk Stage 1	20000	26433	0	2500	USD 462,500	FAIL
LPC (Booster)	1795M11 P01	Booster Disk Stage 2	20000	26433	0	2500	USD 462,500	FAIL
LPC (Booster)	1795M12 P01	Booster Disk Stage 3	20000	26433	0	2500	USD 462,500	FAIL
LPC (Booster)	1795M13 P01	Booster Spool	30000	26433	3567	0	—	PASS
HPC	1796M01 P01	HPC Disk Stage 3	15000	26433	0	2500	USD 462,500	FAIL
HPC	1796M02 P01	HPC Disk Stage 4	20000	26433	0	2500	USD 462,500	FAIL
HPC	1796M03 P01	HPC Disk Stage 5	20000	26433	0	2500	USD 462,500	FAIL
HPC	1796M04 P01	HPC Disk Stage 6	20000	26433	0	2500	USD 462,500	FAIL
HPC	1796M05 P01	HPC Disk Stage 7	25000	26433	0	2500	USD 462,500	FAIL
HPC	1796M06 P01	HPC Disk Stage 8	25000	26433	0	2500	USD 462,500	FAIL
HPC	1796M07 P01	HPC Disk Stage 9	25000	26433	0	2500	USD 462,500	FAIL
HPC	1796M08 P01	HPC Spool (3-4)	30000	26433	3567	0	—	PASS
HPC	1796M09 P01	HPC Spool (5-9)	30000	26433	3567	0	—	PASS
HPT	1797M01 P01	HPT Disk Stage 1	15000	26433	0	2500	USD 462,500	FAIL
HPT	1797M02 P01	HPT Disk Stage 2	20000	26433	0	2500	USD 462,500	FAIL
HPT	1797M03 P01	HPT Stage 1 Blade (set)	10000	26433	0	2500	USD 462,500	FAIL
HPT	1797M04 P01	HPT Stage 2 Blade	10000	26433	0	2500	USD 462,500	FAIL

		(set)						
LPT	1798M01 P01	LPT Disk Stage 4	30000	26433	3567	0	—	PASS
LPT	1798M02 P01	LPT Disk Stage 5	30000	26433	3567	0	—	PASS
LPT	1798M03 P01	LPT Disk Stage 6	30000	26433	3567	0	—	PASS
LPT	1798M04 P01	LPT Disk Stage 7	30000	26433	3567	0	—	PASS
LPT	1798M05 P01	LPT Shaft	30000	26433	3567	0	—	PASS

5. COMPENSATION SUMMARY

Item	Calculation	Amount (USD)
Engine No.1 EGT shortfall (8°C)	8°C × USD 45,000/month equivalent × 9 months = USD 405,000 per Sched. 5	USD 405,000
Engine No.2 EGT	Meets minimum — no compensation due	USD 0
LLP shortfall (all modules combined)	Per LLP table above at USD 185/FC	TBC per final LLP calc
Open structural repairs (2)	2 items × USD 5,000/day × 45 days estimated	USD 450,000
MEL overdue items (2)	2 items × USD 5,000/day × 15 days estimated	USD 150,000
NLG overhaul overdue (4 months)	4 months × USD 18,000/month	USD 72,000
Economy carpet replacement	Lump sum per Schedule 5 Part II	USD 28,000
2 Business Class unserviceable seats	Lump sum per Schedule 5 Part II	USD 15,000
IFE screens non-functional (14)	14 × USD 3,000	USD 42,000
TOTAL COMPENSATION DUE FROM LESSEE		USD 1,162,000+

6. APU / LANDING GEAR STATUS

Component	Value	Required	Status
APU Hours since HSI	1,802 APU-H	Max 4,000 / 24 months	PASS
Last APU HSI Date	2028-04-10	Within 24 months (16 months ago)	PASS
APU Cold Start	26 sec to idle	Max 30 sec	PASS
NLG — months since overhaul	124 months	Max 120 months	FAIL — 4 months overdue
LH MLG — months since overhaul	118 months	Max 120 months	PASS — 2 months remaining
RH MLG — months since overhaul	118 months	Max 120 months	PASS — 2 months remaining

IN WITNESS WHEREOF the parties have executed this document as of the date first written above.

LESSOR INSPECTOR	LESSEE INSPECTOR	INDEPENDENT INSPECTOR
By: _____	By: _____	By: _____
Name: Declan Murphy	Name: James Parrish	Name: Dr. Clara Santos

Title: Chief Inspector	Title: VP Engineering	Title: AeroDynamic Advisory
Date: 2028-10-31	Date: 2028-10-31	Date: 2028-10-31