TM 1-1520-238-23P C02 SECTION II




Figure 656. Group 11 Pitch Control Installation, Tail Rotor (Part 1) 7–311527000