Daily Works Management RCA & CAPA

Date	Issue/Problem Description	Root Cause Analysis (RCA)	Corrective Action (CA)	Preventive Action (PA)	Responsible Person/Team	Target Completion Date	Status	Review/Follow-up Date
	Machine breakdown on Line 1	Root cause: Improper maintenance schedule and lack of spare parts availability.	Immediate corrective action: Perform emergency maintenance and replace faulty components.	Preventive action: Revise maintenance schedule and ensure spare parts are stocked.	Maintenance Team		In Progress	
	Delay in material supply from Supplier X	Root cause: Supplier delay due to transportation issues.	Immediate corrective action: Contact Supplier X and expedite the delivery process.	Preventive action: Develop a second supplier relationship and implement buffer stock for critical materials.	Procurement Team		Completed	
	High defect rate in Product Y	Root cause: Inconsistent machine calibration leading to product defects.	Immediate corrective action: Recalibrate machines and inspect affected products.	Preventive action: Establish a routine calibration schedule and train operators on proper	Quality Assurance Team		Pending Approval	

				calibration procedures.				
	Excessive energy consumption in CNC machines	Root cause: Machines running idle during non-peak hours.	Immediate corrective action: Adjust machine schedules and optimize usage.	Preventive action: Implement energy-saving practices and install energy monitoring tools for better tracking.	Operations Manager		In Progress	
	Worker injury on Assembly Line 2	Root cause: Lack of proper PPE and unsafe work practices.	Immediate corrective action: Provide PPE to workers and stop production to address safety concerns.	Preventive action: Conduct safety training sessions and enforce PPE usage.	Safety Officer		Open	