1. Objective

To ensure adequate Daily Works Management w.r.t Production, Quality, Cost & Delivery within the premises of DEVBHOOMI TEMPLE FLOWERS REPROCCSSING PROJECT.

2. Scope

This procedure covers all Production & QA activities within the boundaries of DEVBHOOMI TEMPLE FLOWERS REPROCCSSING PROJECT.

3. Responsibility

Production I/c, QA I/c & Dispatch I/c

4. Method:

1) Production I/c shall prepare & issue the "Daily work plan" for each section of the Production i.e. Parboiling Area, Milling Area, Dispatch etc.
2) Daily Work Plan shall be prepared considering the pending delivery orders & expected customers orders.
3) Daily Work plan shall include the Item details & Quantity to be produced.
4) Same shall be displayed on Planning Board along with till date production in the month, backlog, if any, etc.
5) At the end of the day, section I/c shall update this planning board with production data of the day.
6) Display board shall be placed in IQC & OQC areas for updating the data related to daily inspection & rejection data along with monthly cumulative rejection & COPQ (Broken %) data also.
7) Production Manager shall plan the dispatch activity on customer shipment schedule basis, as per committed delivery schedules.
8) Plan shall be shared with & communicated to all concerned person through display in the packing area.
9) Board shall be updated by Operation Manager/Supervisor, upon every dispatch done from the plan.
10) Performance of DWM (Daily Works Management) activities shall be discussed in the daily meetings, in presence of Production Manager.
11) Necessary RCA & Corrective actions shall be taken in case; DWM activity is not meeting its defined targets for the 3 days back to back.

12) Effectiveness of the DWM, RCA & corrective actions shall be reviewed by Senior Management (Director) through periodic Management review meetings.

Record Ref:

1. Daily Work Plan
2. Inspection Plan & COPQ Data
3. Weekly Dispatch Plan
4. Action Plan
5. Minutes of the meeting