S.O.P. ON CRITICAL PROCESS

Purpose:

To describe a procedure required within factory premises to identify, establish, verify and monitor a Critical Process.

Scope:

Production area, raw material and finished goods storage area, Quality checking area and maintenance area.

Responsibilities:

Plant In-charge, Production supervisor & Quality executive.

Procedure:

Based on Hazard Assessment, appropriate combination of control measures shall be selected which are capable of preventing, eliminating or reducing hazard to defined levels. Following procedure is to be followed

- Identified Control Measures to manage critical process is Cross verification of design code given by the customer is same to that of the design code available with us.
- First Quality Manage verify the requirement of customer
- Cross verification of design code available in our data having the same design to the customer requirement will be done.
- Operator will check that the design code set in the software contains same design as that of the customer or not. This can be done with the help of the issue slip, which contain all the information (Design code, quality, reference design, colour etc.)

- If NC raise after applying the CP than immediate correction is holding the production.
- Corrective action is cross verification of the data provided by the customer matches the data available in issue slip and same is fed in the software.
- Quality records, purchase order and issue slips Records are to be maintained.

Records:

Sr. No.	Name of record	Document number	Location/ Custodian
1	Quality record	01	Q.M. / Plant Incharge
2	Issue Slips	02	Q.M. / Plant Incharge

Prepared by	Checked by