

Air Traffic Management Contingency Plan



CJLIA/ATS/MA/007 JANUARY 2019

Version 1

CONTROLLED DOCUMENT



TABLE OF CONTENTS

Forwa	ırd	3
Docun	nent Approval and Issue Status	4
Manua	al Holders	5
Amen	dment Procedures	6
Record	d of Amendments	7
Lis of A	Affected Pages	8
List of	Abbreviations	9
Safety	and Quality Statement	10
Staff R	Responsibilities	11
1.	Objective	12
2.	ATS Units, Centres, States and FIR's Affected	12
3.	Management of the Contingency Plan	13
4.	Contingency Routes and Procedures	15
5.	Air Traffic Management and Contingency Procedures	15
6.	Pilot and Operator Procedures	19
7.	Communication Procedures	20
8.	Aeronautical Support Services	20
9.	Search and Rescue Alerting	21



FORWARD

- This Contingency Plan forms part of the overall national contingency planning for Clayton J. Lloyd International Airport (CJLIA) Anguilla in accordance with the provisions of Annex 11 to the Convention on Civil Aviation. The Plan, and any activation of the Plan, is authorised by Air Safety Support International ASSI.
- The Plan provides for the safe continuation of air traffic within CJLIA CTR during periods when ATS may be disrupted or unavailable, or when airspace may be affected by volcanic ash cloud, radioactive cloud, severe weather events or military activity.
- The Plan has been developed in cooperation and collaboration with airspace users and civil aviation authorities responsible for adjacent airspaces and FIRs.
- The Plan will be activated by NOTAM as far in advance as is practicable. In the event that such prior notification is impracticable the Plan will be activated by the designated authority using the most expeditious alternative means available.

January 2019 Version 1 Page | 3



DOCUMENT APPROVAL AND ISSUE STATUS

The Signatures below certifies that this document has been reviewed, accepted and demonstrates that the signatories are aware of all the requirements contained herein and are committed to ensuring their provision.

new of st	Name	Position	Signature	Date
Created/ Prepared by	Roshima Roberts	Air Traffic Services Manager	Makens	14/01/2019
Reviewed by	Jabari Harrigan	Executive Airport Manager		Jan 14 2019
	Kendell Richardson	Quality Assurance Manager	Male	1/14/2019
Approved by	F. Marcel Fahie	Accountable Manager	Latoplalie	1/02/19

MANUAL HOLDERS

This page provides a list of the names and contact information of all persons that is provided with a copy of this manual, internal and external.

	INTERNAL				
Quality Assurance Manager Kendell Richardson	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384 Cell 264 584 9648	Master Document		
Accountable Manager Fabian M Fahie	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384 Cell 264 584 1437	Copy # 1		
Executive Airport Manager Jabari Harrigan	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384 Cell 264 584 9697	Copy # 2		
Operations Manager	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384 Cell 264 584 9697	Copy # 3		
Air Traffic Services Manager Roshima Roberts	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384 Cell 264 584 9974	Copy # 4		
Safety Manager Asha George	P.O. Box 1382 The Valley AI-2640	(W) 264 497 2384	Copy # 5		
Air traffic Services Unit	P.O. Box 1382 The Valley Al-2640	(W) 264 497 2384 Ext 2351	Copy # 6		

EXTERNAL			
ATS Inspector	ASSI	44129389-7033	Copy # 7
Sarah Lee			

AMENDMENT PROCEDURES

The Quality Assurance Manager is responsible for the issuance and control of amendments to this manual. Additionally, the Quality Assurance Manager is also responsible for the safe custody of the approved master copy of all documents produced by the Clayton J Lloyd International Airport. Notwithstanding, all document authors are ultimately responsible for the development and amendment of the manuals written by them.

The distribution of the approved amendment(s) takes place at least 14 (fourteen) days prior to the implementation of the amendment(s). Within 7 (seven) working days after the issue of approved amendment all manual holders must provide confirmation to the Quality Assurance Manager that the required amendment action has been completed by returning the Amendment Return Slip (ARS), signed and dated by the individual responsible for amending the manual. A copy of the ARS can be found in Appendix B. The returned ARS should be accompanied by the obsolete page or section of the document being amended.

Each amended page issued by the Quality Assurance Manager shall be formatted as follows:

- 1. Display the amendment number and date (AMD: 001/05/12) at the bottom on the footer, which will also be recorded on the record of amendments page.
- 2. All amendments will be identified by a change line (black vertical line) in the left margin where changes to the paragraph or wording are made.

All amendments are recorded in the record of amendments table and the list of affected table.



RECORDS OF AMENDMENTS

Amendments				
NUMBER	DATE APPLICABLE	DATE ENTERED	ENTERED BY	ORGANIZATION



LIST OF AFFECTED PAGES

PAGE	DATE	AMENDED SECTION	PAGE	DATE	AMENDED SECTION



LIST OF ABBREVIATIONS

AASPA Anguilla Air and Sea Ports Authority

ARP Aerodrome Reference Point

ATC Air Traffic Control

ATCO Air Traffic Control Officer

ATM Air Traffic Management

ATS Air Traffic Services

CJLIA Clayton J Lloyd International Airport

CTR Control Zone

FIR Flight Information Region

ICAO International Civil Aviation Organization

OTARs Overseas Territories Aviation Requirements

ATSM Air Traffic services Manager

VCR Visual Control Room

SAFETY AND QUALITY STATEMENT

The management and staff of the Clayton J. Lloyd International Airport (CJLIA) recognize and embrace as our foremost duty the pursuit and achievement of sustained success in the operation of the aerodrome. That success depends critically on producing an all around high quality service, with safety as the central focus.

Our team aims to master the systematic, professional and safe conduct of operations at the CJLIA. Fundamental to success, is managers' discharge of their leadership responsibilities and their technical and administrative duties that meet or exceed the CJLIA's quality assurance and safety standards. It is also vital that the rank and file staff perform consistently at or above the required quality standards and work to ensure that aerodrome operations meet and exceed the applicable international aviation industry safety standards.

We will build and maintain strong positive and productive relationships with our customers and stakeholders through the steady implementation and improvement of our *Safety Management System* (SMS) and our *Quality Management System* (QMS) and the programmes based thereon.

Our Board of Directors and the Management Team are responsible for ensuring that all staff are thoroughly educated on the Airport's safety policy, standards, procedures and practices. Managers and staff are held accountable for their actions and are required to comply with all international and national standard operating procedures (SOP), policies and regulations.

The management of the Clayton J Lloyd International Airport is committed to and focused on:

- Establishing and maintaining a robust Safety Management System (SMS) and Quality
 Management System (QMS) that are continuously reviewed and revised as part of the
 improvement process.
- Complying with, achieving and where possible, exceeding the regulatory standards for safety and quality at the CJLIA aerodrome.
- Securing the necessary resources to continually engage in reducing and/or eliminating identified hazards.
- Creating, implementing, maintaining and upgrading internal audit programmes that identify areas in which improvement is necessary and instituting corrective measures.
- Ensuring high quality airport operations that meet the standards in a safety conscious environment.

As the Accountable Manager, I am committed to pursuing the *Safety* and *Quality* Policies of the CJLIA, which are approved and owned by the Board of the Anguilla Air and Sea Ports Authority. The successful implementation of these policies depends variously on every employee of the Clayton J. Lloyd International Airport, at every level and function of the organization.

F. Marcel Fahie Accountable Manager

STAFF RESPONSIBILITIES

Employees

All employees of the Anguilla Air and Sea Ports Authority shall:

- a. Comply with all policies and procedures as it relates to the document control manual.
- b. Comply with all relevant job related documents.
- c. Comply with the requirements of the various established CJLIA policies and procedures.
- d. If required, seek clarification from the appropriate manager responsible for the development and implementation of various processes within the department.
- e. Be aware of current versions of documents and how to access such documents

Managers

All managers are responsible for:

- a. Clarifying issues employees may have as it relates to understanding any part of a document; or to assist the employee in obtaining clarification the document author or one of the reviewers.
- b. Developing and establishing new policies or other documents as required, and ensure adherence to the policy implemented.
- c. Ensuring that any new or revised policy or other document is produced in the approved format which is laid out in the Document Control Procedures Manual.
- d. Presenting any new or revised document to the appropriate board/committee for review and approval.
- e. Maintaining a database of all documents under their responsibility
- f. Maintaining a file of current approved and signed copies of documents under their responsibility
- g. Ensuring latest versions of documents are accessible to all staff members under their responsibility.

1. OBJECTIVE

- 1.1 The Air Traffic Management (ATM) Contingency Plan for Clayton J Lloyd International Airport details arrangements to ensure the continued safety of air navigation in the event of partial or total disruption of air traffic services in the CJLIA CTR in accordance with ICAO Annex 11 Air Traffic Services. The Contingency Plan provides the ATS procedures that will allow aircraft operators to operate within CJLIA CTR during periods of limited or no ATS, as far as is practicable.
- 1.2 This plan relates to all arrival/departure of aircraft to and from CJLIA and transit traffic in CJLIA CTR.

2. ATS UNITS, CENTRES, STATES AND FIRS AFFECTED

- 2.1 In the event that Clayton J. Lloyd International Airport activates this Contingency Plan, the Antigua ATS unit, the San Juan ATS unit, the civil aviation authorities of adjacent ATS units, Centres, States or FIRs affected will be notified in accordance with the LETTER OF AGREEMENT or these procedures. The adjacent ATS units, Centres, States or FIRs directly affected by this Contingency Plan are as follows:
 - a. PRINCESS JULIANA INTERNATIONAL AIRPORT ATS UNIT
 - b. V.C. BIRD INTERNATIONAL AIRPORT ACC/ATS UNIT
 - c. LUIS MUÑOZ MARÍN INTERNATIONAL AIRPORT ACC/ATS UNIT
- 2.2 The contact details of the civil aviation authorities, organisations and ATS units are contained in **Appendix A.** These details should be kept up to date and regularly reviewed.

3. MANAGEMENT OF THE CONTINGENCY PLAN

- 3.1 The contingency measures set out in this Plan are applicable in cases of planned and unexpected interruptions in ATS caused by natural occurrences or other circumstances, which, in one way or another, may impair or totally disrupt the provision of ATS and/or of the related support services in the CJLIA CTR.
 - 3.2 The following arrangements have been put in place to ensure that the management of the Contingency Plan provides for flights to proceed in a safe and orderly fashion within the CJLIA CTR, as far as practicable.

Clayton J. Lloyd Management Team

- 3.4 The Clayton J. Lloyd Management Team includes representation from the following:
 - a. AIR TRAFFIC SERVICES UNIT- ATC, MET & AIS
 - b. AIRPORT MANAGER
 - c. QUALITY ASSURANCE MANAGER
 - d. SAFETY MANAGER
 - e. SECURITY MANAGER
 - f. REPRESENTATIVE FROM AASPA
- 3.5 Terms of Reference for the Clayton J. Lloyd Management Team and the contact details of its members are provided in Appendix A

The Clayton J. Lloyd Management Team shall oversee the conduct of the Contingency Plan and in the event that the CJLIA ATS is disrupted for an extended period, make arrangements for and facilitate the temporary relocation of the ATS to the Princess Juliana ATS UNIT, where possible and oversee the restoration of CJLIA ATS.

Under the circumstances described and when deemed necessary by the CJLIA ATS (or under the circumstances described in its Terms of Reference and when deemed necessary) and as soon as practicable in advance of, or after the commencement of a contingency event causing disruption to CJLIA has occurred, the CJLIA ATS shall convene the Central Coordinating Committee, by the most expeditious means appropriate for the situation, e.g. by telephone or web-based conference.



- 3.6 The ATM Operational Contingency Group (AOCG) function will be convened by the Clayton J. Lloyd Management Team with a primary responsibility to oversee the day to day operations under the contingency arrangements, and coordinate operational ATS activities, during hours of operation, throughout the contingency period. The terms of reference of the AOCG will be determined by the C J. Lloyd Management Team. The AOCG will include any necessary specialist personnel input from the following disciplines:
 - Air Traffic Service (ATS)
 - Aeronautical Telecommunication (COM)
 - Aeronautical Meteorology (MET)
 - Aeronautical Information Services (AIS)
 - ATS equipment maintenance service provider (CNS)

The AOCG functions shall include:

- i) review and update of the Contingency Plan as required;
- ii) keep up to date regarding the contingency situation;
 - iii) organise contingency teams in each of the specialised areas;
 - iv) keep in contact with and update all affected airspace and system users, customers and other relevant stakeholders.
 - v) exchange up-to-date information with the adjacent ATS authorities concerned to coordinate contingency activities;
 - vi) notify the designated organisations of the contingency situation sufficiently in advance and/or as soon as possible thereafter;
 - vii) take necessary action for issuing NOTAMs according to this plan or as otherwise determined by the contingency situation. Where the contingency situation is sufficiently foreseeable the relevant NOTAMs will be issued 48 hours in advance of the contingency events. NOTAM templates are provided in **Appendix A**.

4. CONTINGENCY ROUTES AND PROCEDURES

4.1 In the event of disruption of the ATC services provided by CJLIA ATS UNIT, contingency routes and procedures will be specified to ensure safety of flight and to facilitate limited flight operations commensurate with the prevailing conditions. Existing ATS routes and procedures form the basis of the contingency routes and procedures to be used, and additional PPR restrictions may be applied to limit the number of aircraft operating simultaneously in the system under reduced air traffic services. Additional unpublished contingency routes and procedures may be developed tactically by the AOCG and promulgated by NOTAM as and when circumstances require, such as in the case of volcanic ash cloud, radioactive cloud or severe weather event. Any such amendments to routes and procedures will be notified to, and agreed with, the adjacent ATS units, Centres, States and FIRs specified in Paragraph 2, as appropriate.

If circumstances dictate, domestic flights and international flights that have not yet departed may be temporarily suspended until a full assessment of the prevailing conditions has been determined and sufficient air traffic services restored. A decision to curtail or restart these operations will be made by the CCC.

5. AIR TRAFFIC MANAGEMENT AND CONTINGENCY PROCEDURES

Reduced ATS and Provision of Flight Information Services (FIS) and/or Aeronautical Radio Station Service

- 5.1 During the contingency period ATS including ATC may not be available. In cases where services are not available, a NOTAM will be issued providing the relevant information, including an expected date and time of resumption of service. The Contingency Plan provides for limited flight information and alerting services or an Aeronautical Radio Station to be established by CJLIA ATS UNIT.
- 5.2 In the event that the CJLIA ATS is being interrupted. Princess Juliana ATS will be responsible for providing all ATS in CJLIA CTR until further information is presented.

ATS Responsibilities

- In the event that ATS cannot be provided in the CJLIA a NOTAM shall be issued indicating the following:
 - a) time and date of the beginning of the contingency measures;
 - b) airspace available for landing and overflying traffic and airspace to be avoided;
 - c) details of the facilities and services available or not available and any limits on ATS provision (e.g., APPROACH, TOWER, FIS, Aeronautical Radio Station), including an expected date of restoration of services if available:
 - d) information on the provisions made for alternative services;
 - e) Applicable ATS routes and procedures, AIP-published, or tactically defined contingency routes or procedures.
 - f) any special procedures to be followed by neighbouring ATS units not covered by this Plan;
 - g) any special procedures to be followed by pilots; and
 - h) any other details with respect to the disruption and actions being taken that aircraft operators may find useful.
- 5.4 NOTAM pro-forma are provided at **APPENDIX A**.
- In the event that the CJLIA NOTAM Office is unable to issue the NOTAM, the alternate International NOTAM Office at Piarco Trinidad and Tobago will take action to issue the contingency NOTAM upon notification by the CJLIA NOTAM of fice.

Aircraft Separation

5.6 Aircraft separation criteria, where applicable, will be in accordance with the *Procedures* for Air Navigation Services-Air Traffic Management (PANS-ATM, ICAO Doc 4444) and the Regional Supplementary Procedures (ICAO Doc 7030).

Airspace Classifications

5.7 Depending on the degree of disruption, airspace classifications may be changed to reflect the reduced level of services. Changes to airspace classification will be notified by NOTAM.

Aircraft Position Reporting

- 5.8 The primary means of communication will be by VHF radio.
- 5.9 Traffic Information Broadcast by Aircraft (TIBA) procedures shall apply when ATC is unavailable. The TIBA is part of the contingency PPR briefing which gives the relevant information to all users. Details of TIBA procedures and communications requirements are provided in [Attachment B to Annex 11 to the Convention on Civil Aviation reproduced in **Appendix A** and will be supported by the provision of an Aeronautical Radio Station where possible.

5.10 The TIBA frequency shall be as follows:

The airspace will revert to Aeronautical Radio operations where the service will be provided via use of handheld and base radio operating on frequency 118.5Mhz. The temporary arrangement to contact adjacent units such as Juliana/San Juan will be done via telephone line. Vehicles requiring crossing will monitor 118.5MHz and state that they will be crossing the runway. Air traffic control clearances will be passed to the CJLIA radio operators which will be issued on behalf of the adjacent ATC unit where the read back will be done full to the issuing authority. The pilot is to read back, in full, the clearance relayed by the radio operator.

When an Aeronautical Radio Station is temporarily established the call sign used shall be "Anguilla Radio" to differentiate from the normal ATC provision on the published frequency.

Procedures for ATS Units

- 5.11 CJLIA ATCU will follow their unit instructions and activate the appropriate level of contingency procedures in line with this Plan and any other relevant LoAs or MoUs. These procedures include the following:
- a) Where ATS provided by CJLIA ATS UNIT may be reduced or disrupted by a short-notice contingency event, ATC will inform pilots of the emergency condition and advise if it is likely that the ATC facility will be evacuated and ATS suspended. In the event of it becoming necessary to evacuate the building, the unit evacuation procedures will be activated, and time permitting, controllers will make an emergency evacuation transmission on the radio frequency in use providing pilots with alternate means of communication;
 - b) during the period the contingency procedures are in effect, flight plan and other aircraft movement messages must continue to be transmitted by operators to CJLIA ATS UNIT via the AMHS using normal procedures;



- c) on notification by CJLIA ATS unit, adjacent ATS units, Centres, States and FIRs specified in Paragraph 2, as appropriate, will activate any of the contingency procedures agreed via an LoA or MoU.
- d) prior to entry to the CJLIA CTR during contingency operations PPR must be obtained from CJLIA authority, and flights must comply with the ATC clearances, procedures and communications instructions issued by the ATC authority responsible for the airspace immediately adjacent to the contingency airspace.
- e) coordination of aircraft boundary estimates and levels by the adjacent ATC authority responsible for aircraft entering the CJLIA CTR shall be in accordance with the agreed procedures as detailed in the LOA or as otherwise agreed as part of the contingency operations.

Transition to and from Contingency Operations

- 5.12 In the event of airspace closure that has not been promulgated, ATC should, if possible, broadcast to all aircraft in their airspace, what airspace is being closed and to stand by for further instructions.
- 5.13ATS providers should recognize that when closures of airspace or airports are promulgated, individual airlines might have different company requirements as to their alternative routings. ATC should be ready to respond to any request by aircraft and react commensurate with safety.

Transfer of Control and Coordination

Unless otherwise specified in the Plan, relevant LOA or agreed tactically as part of the contingency operation, transfer of control and communication should be in accordance with standard operating procedures.

6. PILOT AND OPERATOR PROCEDURES

Filing of flight plans

6.1 Flight planning requirements detailed in the Eastern Caribbean AIP continue to apply during contingency operations, except where modified by the contingency procedures specified by ATC and/or by NOTAM.

Flight approval

6.2 Aircraft operators must obtain PPR from the CJLIA Authority prior to operating flights within the CJLIA CTR. During the period of activation of this Contingency Plan the adjacent ATS authority will provide normal ATC clearances for aircraft to enter the CJLIA CTR. The adjacent ATS authority is not responsible for coordination or provision of PPR for the CJLIA CTR. The operator must ensure any PPR has been obtained.

Pilot operating procedures

- 6.3 Pilots will continue to make or broadcast routine position reports in line with normal ATC reporting procedures.
- 1.4 Pilots of aircraft operating in the CJLIA CTR during contingency operations shall comply

with the following procedures:

- flights are to flight plan using any specified contingency routes according to their airport of origin and destination;
- aircraft are to operate as close as possible to any assigned contingency route;
- a continuous communications watch shall be maintained on the contingency frequency as notified
- in the absence of an ATS, aircraft position reports and other information shall be broadcast in accordance with TIBA procedures defined in the CJLIA PPR briefing;
- aircraft navigation and anti-collision lights shall be displayed;
- except in cases of emergency or for reasons of flight safety, pilots are to, during their entire flight within CJLIA CTR, comply with any ATC clearance specified.
- not all operational circumstances can be addressed by this Contingency Plan and pilots are to maintain a high level of alertness when operating in the contingency airspace and take appropriate action to ensure safety of flight.
- Pilots shall continuously guard the VHF emergency frequency 121.5 MHz and should operate their transponder during flight, regardless of whether the aircraft is within or outside airspace where secondary surveillance radar (SSR) is used for ATS purposes. Transponders should be set on the last discrete code assigned by ATC or select code 2000 if no code was assigned.

7. COMMUNICATION PROCEDURES

<u>Degradation of Communication - Pilot Radio Procedures</u>

- 7.1 When operating within the contingency airspace, pilots should use normal radio communication procedures where ATS services are available. Where limited or no ATS is available communications conducted will be in accordance with the communication procedures in this Plan, or as otherwise notified by NOTAM.
- 7.2 If communications are lost unexpectedly on the normal ATS frequencies, pilots should try the next applicable frequency. Pilots should also consider attempting to contact ATC on the last frequency where two-way communication had been established. In the absence of communication with ATC, the pilot should continue to make routine position reports on the assigned frequency, and broadcast positions in accordance with the TIBA procedures.

Communication frequencies

7.3 A list of frequencies to be used for the CJLIA CTR is detailed in Paragraph 5

8. AERONAUTICAL SUPPORT SERVICES

Aeronautical Information Services (AIS)

8.1 The Aeronautical Information Service is available for operations between 1100utc-2100utc. In the event that the AIS office is close the Piarco Office will be called via telephone and details will be given to the office to have any information disseminate on behalf of CJLIA ATS unit.

Meteorological Services (MET)

8.2 Meteorological services are available at the same time as the CJLIA ATC unit opening and closing hours. During contingency operations the CJLIA Meteorological Services will communicate with V.C Bird meteorological Service for assistance in disseminating metrological information.

9. SEARCH AND RESCUE ALERTING

Notification and Coordination

9.1 The SAR authority responsible for the CJLIA CTR is the Fort de France Rescue Coordination Centre (RCC)

Telephone 011596596709292/011596596731616

Fax 011596596632450

AFTN TFFFZPZX

Email antilles@mrccfr.eu



APPENDIX A

Clayton J. Lloyd International Airport Contingency Plan Information

Contact Details for C J. Lloyd Management Team

Name	Contact Number
Air Traffic Services Manager	1-264-584-9974
Quality Assurance Manager	1-264-584-9648
Safety Manager	1-264-584-9779
Security Manager	1-264-584-9756
Representative from AASPA	1-264-584-1437

Coordinating Bodies

Name	Contact Number
Princess Juliana International Airport-ATS Unit	1-721-545-2160 or 1-721-545-5753
V C Bird International Airport-ACC/ATS Unit	1-268-462-4703
Luis Muñoz Marín International Airport-ACC/ATS Unit	1-787-253-8731/2

NOTAM

"ATC not available. An Aeronautical Station has been established for the purposes of providing weather and traffic information to assist pilots operating on and in the vicinity of the aerodrome. It is available during the notified operating hours of the airport; Anguilla Radio on frequency 118.500, DOC 25nms, SFC-4000ft.

Traffic Information Broadcasts by Aircraft Procedures- see attachment B in Annex 11.