


Periferical Assembly

P 08 1 20



1. Periferical Assembly (Production)

All the periferical contained in the final products are constructed or finalized.

2. Assembly Line 1 & 2 (Operators)

The different periferical parts are assembly in the specific areas according the planning instructions

3. Assembly (Operators)

Assembly the specific parts "step by step" acording to each Assembly Manual: [03C03] Manufacturing-WorkStations - OneDrive (sharepoint.com)

4. Validation Process (Qualified Operator)

After the assembly a bunch of validation tests must be preformed according with the instruction of Addam software.

If occurs a NOK on the validation process, then the failure should be analysed and identied if it's possible to do a internal repair, if not, the part should be adressed to the NC Warehouse for further evaluation.

If the validation is OK, a report should be emitted and the part adressed to the stock warehouse.

Creation Date: 02/09/2024

Revision Date: 02/09/2024

Macro Process: 08 - Operations - Production

Process: 08 1 - Production

Procedure: P 08 1 20 - Periferical Assembly

Creator: C.Santos Approver: M.Sousa