

Repair Estimate — Metro Auto Body

Related Policy ID: POL-2024-0098213
VIN: 1HGCM82633A004352
Incident Date: 2024-03-14

Line Items

Description	Cost
Front bumper replacement	\$850.00
Headlight assembly	\$420.50
Labor - body repair	\$682.50
Paint and materials	\$310.00
Total	\$2,263.00