

Software Code: 01DV0000000145	Product family: VKP80III Linux CUPS Driver
Last available release: 2.18	

Driver changelog

REL.	DATE	RELEASE NOTES
2.18	01/Jul/2025	Bug fixes and Improvements: Modified support for roll page in newer OS
2.17	05/May/2024	New features and improvements: - Added possibility to eject directly the page after printing Bug fixes and Improvements: - Fixed issue with PTP functions – firmware 6.22 required for printer
2.12	02/Apr/24	New features and improvements: - Added dithering - Change library for PTP functions

Additional Notes: