

JP1 and 3 should be right-angle type headers mounted to the bottom of the board rather than the vertical headers in the design