

# **Supporting 100BASE-FX Fiber Media for Microchip's Ethernet Controller, Switch and EtherCAT Controller**

Author: Anant Dalimkar

Microchip Technology, Inc.

# INTRODUCTION

Microchip provides design solutions targeted to support next generation Ethernet switches, EtherCAT<sup>®</sup> industrial controllers and a 10/100 Industrial Ethernet MAC/PHY controllers. The Ethernet switch products are divided into host bus and MII categories with the host bus versions supporting a full featured Ethernet MAC residing behind the switch fabric. The non-host bus versions support various MII, RMII and Turbo MII options with 1 and 2 port options.

The following table lists the various products available.

Part Number	Description
LAN9250	10/100 Industrial Ethernet Controller & PHY
LAN9252	2/3-Port EtherCAT Slave Controller with Integrated Ethernet PHYs
LAN9352	2-Port 10/100 Managed Ethernet Switch with 16-Bit Non-PCI CPU Interface
LAN9353	3-Port 10/100 Managed Ethernet Switch with Single MII/Turbo MII or Dual RMII
LAN9354	3-Port 10/100 Managed Ethernet Switch with Single RMII
LAN9355	3-Port 10/100 Managed Ethernet Switch with Dual MII/RMII/Turbo MII

This document will highlight the design differences needed to implement 100BASE-FX fiber media on Microchips' Ethernet Controller, Switch and EtherCAT Controller.

This document includes the following topics:

- Feature Differences for 100BASE-FX on page 3
- EtherCAT Over Optical Links (FX) Applicable Only for LAN9252 on page 9

# **Audience**

The target audiences for this document are hardware design engineers and managers using Microchips' Ethernet Controller, Switch and EtherCAT Controller in a 100BASE-FX application.

# References

The following documents should be referenced when using this application note. See your Microchip representative for availability.

- · LAN9250 Datasheet
- LAN9252 Datasheet
- LAN9352/LAN9354/LAN9355 Datasheet
- LAN9355 Datasheet

# **Terms and Abbreviations**

- MII Media Independent Interface
- RMII Reduced Media Independent Interface
- EEE Energy-Efficient Ethernet
- SFF Small Form Factor
- SFP Small Form Factor Pluggable
- SMI Serial Management Interface
- · MAC Media Access Control
- PHY Physical layer device
- EEE Energy Efficient Ethernet

# FEATURE DIFFERENCES FOR 100BASE-FX

This section describes the hardware and software differences for a designer to implement the new 100BASE-FX fiber media in Microchip's Ethernet Controller, Switch and EtherCAT Controller.

#### **Hardware Details**

100BASE-FX support via external fiber transceiver.

When set for 100BASE-FX operation, the scrambler and MTL-3 blocks are disable and the analog RX and TX pins are changed to differential LVPECL pins and connect through external terminations to the external Fiber transceiver. The differential LVPECL pins support a signal voltage range compatible with SFF (LVPECL) and SFP (reduced LVPECL) type transceivers.

While in 100BASE-FX operation, the quality of the receive signal is provided by the external transceiver as either an open-drain, CMOS level, Loss of Signal (SFP) or a LVPECL Signal Detect (SFF).

# 100BASE-FX ENABLE AND LOS/SD SELECTION

100BASE-FX operation is enabled by the use of the FX mode straps (fx\_mode\_strap\_1 and fx\_mode\_strap\_2) and is reflected in the 100BASE-FX Mode (FX\_MODE) bit in the PHY x Special Modes Register (PHY\_SPECIAL\_MODES\_x).

Loss of Signal mode is selected for both PHYs by the three level FXLOSEN strap input pin. The three levels correspond to Loss of Signal mode for a) neither PHY (less than 1 V (typ.)), b) PHY A (greater such as than 1 V (typ.) but less than 2 V (typ.)) or c) both PHYs [greater than 2 V (typ.)]. It is not possible to select Loss of Signal mode for only PHY B.

If Loss of Signal mode is not selected, then Signal Detect mode is selected, independently, by the FXSDENA or FXSDENB strap input pin. When greater than 1 V (typ.), Signal Detect mode is enabled, when less than 1 V (typ.), copper twisted pair is enabled.

Note: The FXSDENA strap input pin is shared with the FXSDA pin and the FXSDENB strap input pin is shared with the FXSDB pin. As such, the LVPECL levels ensure that the input is greater than 1 V (typ.) and that Signal Detect mode is selected. When TP copper is desired, the Signal Detect input function is not required and the pin should be set to 0 V.

Care must be taken such that an non-powered or disabled transceiver does not load the Signal Detect input below the valid LVPECL level.

TABLE 1: 100BASE-FX LOS, SD AND TP COPPER SELECTION PHY A

FLXLOSEN	FXSDENA	PHY Mode
<1 V (typ.)	<1 V (typ.)	TP copper
	>1 V (typ.)	100BASE-FX Signal Detect (SFF)
>1 V (typ.)	NA	100BASE-FX LOS (SFP)

TABLE 2: 100BASE-FX LOS, SD AND TP COPPER SELECTION PHY B

FLXLOSEN	FXSDENA	PHY Mode
<1 V (typ.)	<1 V (typ.)	TP copper
	>1 V (typ.)	100BASE-FX Signal Detect (SFF)
>2 V (typ.)	NA	100BASE-FX LOS (SFP)

# Signal Detection (SD)

Signal Detection (SD), which requires single-ended 3.3V LVPECL levels and support the Small Form Factor (SFF) optical Module. Signal detect is use to determine the Normal operation, optical signaling detected.

SD is a logical complement of Loss of Signal (LOS).

- · Single Ended LVPECL
  - SD> VLVPECL COMMON MODE Normal Operation, Optical signaling detected
  - SD <VLVPECL COMMON MODE No optical signal detected
- 50Ω Single-ended Impedance

# Loss of Signal (LOS)

Loss of Sync (LOS) which requires CMOS levels and supports the Small Form-Factor Pluggable (SFP) optical module. LOS is an Open Drain/Collector. LOS is a logical complement of Signal Detect (SD).

- · LOS<0.8V Normal Operation Optical signaling detected
- · LOS>2.0V No optical signal detected

LOS (Loss of signal) is an Open Drain/Collector output, which should be pulled up with a 4.7K-10K resistor.

# CONNECTION TO 100BASE-FX FIBER MODULE

The FX mode enables the 10/100Mbps Ethernet PHY transport data over fiber optics medium using Fiber Optics Transceivers (FOT). The FX mode supports two form factors running at 100Mbps. The Small Form Factor (SFF) module can be configured using an AC or DC coupled channel while the Small Form Factor Pluggable (SFP) module can only be configured in an AC coupled channel.

# SFF:

- · DC/AC Coupled
  - 100Ω equivalent TX/RX termination

# SFP:

- · AC Coupled
  - 100Ω TX/RX termination

The FX mode transceivers incorporate an LVPECL differential driver to transmit the 4b5b encoded data, while the receiver supports both LVDS and LVPECL signal levels.


The following block diagrams show a common interface between the 10/100Mbps Ethernet PHY and the FOT for various configurations.

# DC COUPLED (SFF MODULE)

**Note:** DC coupling is recommended for 3.3V FOT modules.

The Jutland FX mode LVPECL output driver always requires a  $50\Omega$  termination. An additional  $16\Omega$  is required to set the proper common mode voltage for the FOT. This configuration works only for 3.3V FOT. If the PHY is required to interface with 5V FOT, the value of the resistor that sets the common mode voltage must change. It is recommended to use DC coupling for 3.3V FOTs. It is also a good practice to place the  $50\Omega$  termination resistor as close to the FOT as possible to minimize noise due to reflection. The Jutland FX mode receiver incorporates the  $50\Omega$  termination resistor external to the PHY to reduce on chip power and have flexibility on the value of the termination resistors to be used with AC coupled channels. If offset is required on the transmitter path, resistor ROFFSET can be added from the TXN pad to ground. The value of the resistor is determined by the amount of offset required. Signal detect is almost always DC coupled, and requires a  $50\Omega$  impedance with a 1.3V common-mode voltage.

FIGURE 1: 100BASE-FX DC COUPLED CONFIGURATION (SFF MODE)




# AC COUPLED (SFF MODULE)

Note: AC coupling is recommended for 5V FOT modules.

The Jutland FX mode LVPECL output driver always requires a  $50\Omega$  external termination. It is a good practice to place the  $50\Omega$  termination resistor as close to the FOT as possible to minimize noise due to reflection. The common mode voltage of the receiver is set to be the same as LVPECL common mode voltage (VDD-1.3V). If offset is required on the transmitter path, increase or decrease the pull up resistor at TD- as compared to the pull up resistor at TD+. The value of the mismatch between the pull up resistors is determined by the amount of offset required by the FOT. If zero offset is required, the value of the two pull up resistors, R1\* & R2\*, at TD+ and TD- are equal. Signal detect should be DC coupled and include a  $50\Omega$  termination set to a common-mode voltage of 1.3V.

FIGURE 2: 100BASE-FX AC COUPLED CONFIGURATION (SFF MODE)



# AC COUPLED (SFP MODULE)

The SFP module operates in a reduced LVPECL signaling level due to the AC couple nature of the channel and the  $100\Omega$  termination resistor embedded within the FOT module. The AC couple capacitor may or may not be embedded within the FOT module. The LVPECL transmitted data signal level will get reduced by half at the FOT input (TD+/-) due to the additional  $100\Omega$  termination. On the receive side, the  $82\Omega/130\Omega$  off chip termination resistors sets the  $50\Omega$  termination as well as the common mode voltage for the receiver. Jutland receiver requires the  $50\Omega$  termination resistors to be placed as close to the Jutland PHY as possible to minimize noise due to reflection. Signal detect should be DC coupled and include a  $50\Omega$  termination set to a common-mode voltage of 1.3V.




FIGURE 3: 100BASE-FX AC COUPLED CONFIGURATION (SFP MODE)

# **Register Settings**

The Physical PHYs comply with the IEEE 802.3 Physical Layer for Twisted Pair Ethernet and can be configured for full/half duplex 100 Mbps (100BASE-TX / 100BASE-FX) or 10 Mbps (10BASE-T) Ethernet operation. All PHY registers follow the IEEE 802.3 (clause 22.2.4) specified MII management register set and are fully configurable.

100BASE-FX operation is enabled by the use of the FX mode straps (fx\_mode\_strap\_1 and fx\_mode\_strap\_2) and is reflected in the 100BASE-FX Mode (FX\_MODE) bit in the PHY x Special Modes Register (PHY\_SPECIAL\_MODES\_x).

# **Fiber Optical Modules**

Several Fiber optical modules may be used with an Ethernet PHY that supports 100Base-FX (IEEE 802.3u): Small Form Factor (SFF) Transceiver

- AFBR-59E4APZ Avago Technologies
- (New 2x5 DIP style Package)

- · Differential LVPECL TX. RX
- Single Ended LVPECL Signal Detect (SD)
- · 3.3V Supply
- · Supported DC Coupling only

# FIGURE 4: SMALL FORM FACTOR (SFF) TRANSCEIVER



Small Form-factor Pluggable (SFP) Transceiver

- FTLF1318P2xCL Finisar Corporation
- Reduced LVPECL TX, RX
- · Open Drain/Collector Loss of Signal
- 3.3V Supply
- · Supported AC Coupling only

# FIGURE 5: SMALL FORM FACTOR PLUGGABLE (SFP) TRANSCEIVER



# **Operational Controls and Indications**

# SUPPORTED FEATURES FOR 100BASE-FX

Because the 100BASE-FX mode uses 100BASE-T resources, its operational controls and indications are those of the 100BASE-T mode, such as LEDs, link status indication, and loopback modes.

- · LED Indication Any LED that supported 100BASE-TX will now support 100BASE-FX indication
- Link Status For Link Status Indication, the Link Status bit Register 1.2 will indicate if a link is present for 100BASE-FX

# FEATURES NOT SUPPORTED FOR 100BASE-FX

Feature not supported in FX mode includes Auto negotiation, AMDIX, TDR, EDPD, and EEE features.

# ETHERCAT OVER OPTICAL LINKS (FX) — APPLICABLE ONLY FOR LAN9252

EtherCAT communication over optical links using Ethernet PHYs is possible, but some requirements of EtherCAT have to be respected, and some characteristics of EtherCAT slave controllers have to be considered.

The intention of this chapter is to share current knowledge about FX operation with EtherCAT.

# **Link Partner Notification and Loop Closing**

The main principle of operation in case of link errors is disabling unreliable links by closing loops. This is automatically performed by the ESCs. The ESCs rely on the LINK MII signal from the PHYs for detecting the link state.

With FX PHYs, it could happen that the Transceiver device is powered, while the PHY (and/or the ESC) is not active. The communication partner would detect a signal, causing him to open the link. All frames will get lost because the PHY (or the ESC) is not operating.

So at least the following two requirements have to be fulfilled, otherwise frames will be lost:

- ESC in reset state → Transceiver disabled
- PHY in reset state → Transceiver disabled

The recommended solution for this issue is to enable the Transceiver with the PHY's reset signal. If the transceiver has no suitable input, the power supply of the Transceiver can be switched off. Since the PHY's reset should be controlled by the ESC's reset output (delayed, see later), the Transceiver will power down while the PHY is in the reset state and also while the ESC is in the reset state. Thus, the ESC and the PHY will be active when the Transceiver gets active, and no frames are lost.

# FAR-END-FAULT (FEF) INDICATION

LAN9252 offer a feature called Far-End-Fault generation/detection. The intention is to inform the link partner of a bad link.

The FEF feature is advantageous for EtherCAT, because the PHYs will only indicate a link when the signal quality is high enough. Without FEF, the EtherCAT slave controllers have to rely on the Enhanced Link detection feature for detecting a low quality link.

Nevertheless, Enhanced Link detection becomes active only after the link is already established, thus, in case of a low quality link, the link status will be toggling on/off (link up  $\rightarrow$  Enhanced link detection tears down link  $\rightarrow$  link up ...). This is sufficient to locate an issue in the network, but it might disturb operation of the remaining network.

So, it is highly recommended to use PHYs which fully implement FEF generation and detection.

# **Standard Link Detection**

The Enhanced link detection restarts auto-negotiation between the PHYs if a certain level of receive errors is reached. With FX PHYs, auto-negotiation is not available (it is a 100Base-TX feature). Typically, PHYs ignore the restart auto-negotiation request. As a consequence, the EtherCAT slave controller waits endlessly for the link to go down. Other PHYs might get into a dead-lock, because auto-negotiation is enabled by the restart auto-negotiation request, but it will not complete due to the FX operation mode.

Thus, Enhanced Link Detection has to be turned off for FX links (unless Enhanced FX Link Detection is used, which is recommended.

# ISSUE: TEMPORARY ENHANCED LINK DETECTION WHILE EEPROM IS LOADING

Enhanced Link Detection is enabled after Reset, and it can only be disabled by EEPROM. This takes about 170 ms. In the meantime, the FX PHYs are powering up. Since they do not need to go through an auto-negotiation sequence, the link (signal detect) comes very early. It is possible that the link is detected, but communication is not possible (RX\_ERR are detected). This can trigger the ESC to restart auto-negotiation before the EEPROM is loaded, resulting in the ESC waiting for the link to go down. This will probably not happen because the PHY ignores this command, so the ESC remains in a dead-lock situation.

The recommended solution to overcome this issue is to power up the FX PHY (and the transceiver) at least 170 ms after the ESC, such as by an additional reset controller with delay or power sequencing (Figure 6 or Figure 7).

Another recommended solution is the Enhanced FX Link Detection on page 10.


Minimum solutions without Enhanced Link Detection:

These two solutions represent the minimum solution for proper power-up and reset operation, but they have drawbacks in detection low quality links. The preferred solution is the Enhanced FX Link Detection, see later.

Standard Link Detection: By Delayed Reset to FX-PHY

RESET to External PHY is delayed by 170 ms after ESC (LAN9252) getting ready.


FIGURE 6: PHY RESET RELEASE DELAY WITH TRANSCEIVER POWER DOWN/RESET



Standard Link Detection: By Power Sequencing

POWER to External PHY is delayed by 170 ms after ESC getting powered up.

FIGURE 7: PHY POWER SEQUENCING WITH TRANSCEIVER POWER DOWN/RESET



# **Enhanced FX Link Detection**

In order to detect erroneous links fast enough, it is desirable to use the error detection principle of Enhanced

Link Detection also for FX PHYs. One possible solution is to use the Enhanced Link Detection logic inside the ESC, and another possible solution is to implement enhanced link detection logic with external logic, such as a CPLD.

LAN9252 ESC does not support Enhanced Link Detection logic for external MII port; hence external logic should implement using micro controller/CPLD.

The preferred solution is to let the ESC count the RX\_ERR of the PHY, and to detect the restart auto-negotiation request of the ESC by some additional logic (CPLD or  $\mu$ Controller etc.) attached to the MII management interface. This logic should reset the PHY and the Transceiver (power-down) for a short time. This reset causes a link down, which will be detected by the local ESC (which will leave its potential dead-lock state), and by the communication partner (link down, loop closed). If this solution is chosen, Enhanced Link Detection can be enabled in the EEPROM.

The MII management interface is still connected to the PHY, the CPLD/ $\mu$ C just snoops the bus. It is possible to use one CPLD/ $\mu$ C for all ports of the ESC. The PHY address has to be evaluated and individual reset outputs for each PHY have to be used.

# PROPOSED SOLUTIONS WITH ENHANCED LINK DETECTION

The following images, Figure 8 and Figure 9, display the proposed solutions with enhanced link detection.

FIGURE 8: CPLD/µC DETECTS AUTO-NEGOTIATION RESTART COMMAND AND RESETS PHY AND TRANSCEIVER






FIGURE 9: CPLD/µC DETECTS AUTO-NEGOTIATION RESTART COMMAND AND POWERS DOWN PHY AND TRANSCEIVER



**Note:** In Figure 9, the CPLD/μC is connected to the nRESET signal of the ESC/PHY to power-down/reset the transceiver while the ESC/PHY is in reset state.

# **APPENDIX A: SCHEMATICS**


FIGURE A-1: SCHEMATIC A: INTERFACE BETWEEN LAN9XXX AND THE SFP (FTLF1318P2) FOT



- **Note 1:** SFP Transceiver FTLF1318P2, TX/RX DATA lines are AC coupled, Hence C1,C2, C3 and C4 are not required externally.
  - 2: Refer to FOT supplier's recommendation regarding the interface between LAN9xxx and FOT. The proposed termination is recommended for AC Coupled Configuration (SFP mode).

    Other terminations could also be applicable, depending on the FOT interface.





- **Note 1:** SFF Transceiver AFBR-59E4APZ, TX/RX DATA lines are AC coupled, Hence C8,C9, C10 and C11 are not required externally.
  - 2: Refer to FOT supplier's recommendation regarding the interface between LAN9xxx and FOT. The proposed termination is recommended for AC Coupled Configuration (SFF mode). Other terminations could also be applicable, depending on the FOT interface.

# APPENDIX B: APPLICATION NOTE REVISION HISTORY

# TABLE B-1: REVISION HISTORY

Revision Level & Date	Section/Figure/Entry	Correction
Rev. A, Sept. 2015	Initial release.	

# THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- Product Support Data sheets and errata, application notes and sample programs, design resources, user's
  guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

# **CUSTOMER CHANGE NOTIFICATION SERVICE**

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

# **CUSTOMER SUPPORT**

Users of Microchip products can receive assistance through several channels:

- · Distributor or Representative
- · Local Sales Office
- · Field Application Engineer (FAE)
- · Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: http://microchip.com/support



NOTES:

# Note the following details of the code protection feature on Microchip devices:

- · Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our
  knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data
  Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- · Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

#### **Trademarks**

The Microchip name and logo, the Microchip logo, dsPIC, FlashFlex, flexPWR, JukeBlox, KEELoQ, Iogo, Kleer, LANCheck, MediaLB, MOST, MOST logo, MPLAB, OptoLyzer, PIC, PICSTART, PIC<sup>32</sup> logo, RightTouch, SpyNIC, SST, SST Logo, SuperFlash and UNI/O are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

The Embedded Control Solutions Company and mTouch are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, BodyCom, chipKIT, chipKIT logo, CodeGuard, dsPICDEM, dsPICDEM.net, ECAN, In-Circuit Serial Programming, ICSP, Inter-Chip Connectivity, KleerNet, KleerNet logo, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, RightTouch logo, REAL ICE, SQI, Serial Quad I/O, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2015, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-63277-836-9

# QUALITY MANAGEMENT SYSTEM CERTIFIED BY DNV = ISO/TS 16949=

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



# **Worldwide Sales and Service**

# **AMERICAS**

Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support:

http://www.microchip.com/ support

Web Address: www.microchip.com

Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455

Austin, TX Tel: 512-257-3370

Boston

Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088

Chicago Itasca, IL

Tel: 630-285-0071 Fax: 630-285-0075

Cleveland

Independence, OH Tel: 216-447-0464 Fax: 216-447-0643

**Dallas** Addison, TX

Tel: 972-818-7423 Fax: 972-818-2924

**Detroit** Novi, MI

Tel: 248-848-4000

Houston, TX Tel: 281-894-5983

Indianapolis Noblesville, IN

Tel: 317-773-8323 Fax: 317-773-5453

Los Angeles Mission Viejo, CA

Tel: 949-462-9523 Fax: 949-462-9608

New York, NY Tel: 631-435-6000

**San Jose, CA** Tel: 408-735-9110

**Canada - Toronto** Tel: 905-673-0699 Fax: 905-673-6509

# ASIA/PACIFIC

Asia Pacific Office Suites 3707-14, 37th Floor Tower 6, The Gateway Harbour City, Kowloon

Hong Kong Tel: 852-2943-5100

Fax: 852-2401-3431 **Australia - Sydney** Tel: 61-2-9868-6733 Fax: 61-2-9868-6755

**China - Beijing** Tel: 86-10-8569-7000 Fax: 86-10-8528-2104

**China - Chengdu** Tel: 86-28-8665-5511 Fax: 86-28-8665-7889

**China - Chongqing** Tel: 86-23-8980-9588 Fax: 86-23-8980-9500

**China - Dongguan** Tel: 86-769-8702-9880

**China - Hangzhou** Tel: 86-571-8792-8115 Fax: 86-571-8792-8116

**China - Hong Kong SAR** Tel: 852-2943-5100 Fax: 852-2401-3431

**China - Nanjing** Tel: 86-25-8473-2460 Fax: 86-25-8473-2470

**China - Qingdao** Tel: 86-532-8502-7355 Fax: 86-532-8502-7205

**China - Shanghai** Tel: 86-21-5407-5533 Fax: 86-21-5407-5066

**China - Shenyang** Tel: 86-24-2334-2829 Fax: 86-24-2334-2393

**China - Shenzhen** Tel: 86-755-8864-2200 Fax: 86-755-8203-1760

**China - Wuhan** Tel: 86-27-5980-5300 Fax: 86-27-5980-5118

**China - Xian** Tel: 86-29-8833-7252 Fax: 86-29-8833-7256

# ASIA/PACIFIC

**China - Xiamen** Tel: 86-592-2388138 Fax: 86-592-2388130

**China - Zhuhai** Tel: 86-756-3210040 Fax: 86-756-3210049

India - Bangalore Tel: 91-80-3090-4444 Fax: 91-80-3090-4123

India - New Delhi Tel: 91-11-4160-8631 Fax: 91-11-4160-8632

India - Pune Tel: 91-20-3019-1500

**Japan - Osaka** Tel: 81-6-6152-7160 Fax: 81-6-6152-9310

**Japan - Tokyo** Tel: 81-3-6880- 3770 Fax: 81-3-6880-3771

**Korea - Daegu** Tel: 82-53-744-4301 Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200 Fax: 82-2-558-5932 or 82-2-558-5934

**Malaysia - Kuala Lumpur** Tel: 60-3-6201-9857 Fax: 60-3-6201-9859

**Malaysia - Penang** Tel: 60-4-227-8870 Fax: 60-4-227-4068

**Philippines - Manila** Tel: 63-2-634-9065 Fax: 63-2-634-9069

**Singapore** Tel: 65-6334-8870 Fax: 65-6334-8850

**Taiwan - Hsin Chu** Tel: 886-3-5778-366 Fax: 886-3-5770-955

Taiwan - Kaohsiung Tel: 886-7-213-7828

**Taiwan - Taipei** Tel: 886-2-2508-8600 Fax: 886-2-2508-0102

**Thailand - Bangkok** Tel: 66-2-694-1351 Fax: 66-2-694-1350

# **EUROPE**

**Austria - Wels** Tel: 43-7242-2244-39 Fax: 43-7242-2244-393

**Denmark - Copenhagen** Tel: 45-4450-2828 Fax: 45-4485-2829

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79
Germany - Dusseldorf

Tel: 49-2129-3766400

Germany - Karlsruhe Tel: 49-721-625370

**Germany - Munich** Tel: 49-89-627-144-0 Fax: 49-89-627-144-44

**Italy - Milan** Tel: 39-0331-742611

Fax: 39-0331-466781 **Italy - Venice** Tel: 39-049-7625286

**Netherlands - Drunen** Tel: 31-416-690399 Fax: 31-416-690340

Poland - Warsaw Tel: 48-22-3325737 Spain - Madrid

Tel: 34-91-708-08-90 Fax: 34-91-708-08-91

**Sweden - Stockholm** Tel: 46-8-5090-4654

**UK - Wokingham** Tel: 44-118-921-5800 Fax: 44-118-921-5820

07/14/15