

## OPS - PT Philips Industries Batam SWS for 4oz Natural Keymodul

Document code	18090-00078008	Version	1	Renewal	0	
Document Change Order	Not Applicable					
Document type	Record					
Document subtype	QMS					
Section	Doc - 3.1.7_Prod&Sys Validate and release designs	[Prod&Sys]				
Template base	Not Applicable					
Document owner	Jannaturrum _ (310147436)					
Author(s)	Not Applicable					
Reviewed date	10 November 2021 07:55 CET					
Approved date	29 November 2021 07:55 CET					

Reviewed date	10 November 2021 07:55 CET			
Approved date	29 November 2021 07:55 CET			
Released date 29 November 2021 07:55 CET				
Next renewal date Not Applicable				
Obsolescence date	Not Applicable			

Related codes Not Applicable	
Not Applicable	

## Reviewed by

Lovely Permata, Vyola (310237591) 09 November 2021 03:15 CET Primawan, Ari (310122728) 10 November 2021 07:55 CET

## Approved by

Anwar, Zuhdi (310213762) 15 November 2021 04:58 CET Hadi Sukoco, Ismo (300231075) 29 November 2021 07:53 CET

Reason for change
This is initial released in DIM. Actual update when upload to DIM is on Revision 2 (previous history refer to CSV-14-062-14005).
Body files
18090-00078008 SWS FOR 4OZ NATURAL KEYMODUL.pdf
QMS ID
QMS-0092

Cover sheet page 2 of 2 Released



CELL	/ AREA : MAIN ASSEMBLY	CYCLE TIME (second)		TAKT TIME	SWIP	SWIP SYMBOL	QUALITY CHECK	SAFETY		
STAT	ION : STATION 1		24		6,5	6				
	Job Element				0,3	-				
No	Activity	Picture	MAN	AUTO WALK		PPE	and Standard La	iyout		
1	English: Take 1 bottle and blow it to the air blow box, and make sure the bottom side of the bottle is not dented. Also, check the visual bottle includes bottle laser, printing on the scale, and printing on the logo.  Bahasa: Ambil 1 buah botol dan blow kedalam box air blow, pastikan bawah bagian bawah dari botol tidak penyok. Juga, cek visual botol termasuk laser		1		SAFETY F Selalu mo	IRST: Think Safe engutamakan kes -customer relatio	ty, Work Safety elamatan, Selalu b n ship always chec	lways working caref ekerja dengan hati- k the result of work ork before being tra	hati. from the	
	botol, cetakan di ukuran, dan cetakan di logo.	V. J.			the next QUALIT	provious process and check the result our work before being transferred to the next process.  QUALITY CONCERN: Supplier - Customer relation ship / Selalu memeriksa hasil pekerjaan dari proses sebelumnya dan memeriksa hasil pekerjaan kita				
2	English: Make sure the air blow function properly so the dirt can come out from the bottle.		4		sebelum	diberikan ke pro	Dar No ;	Propered Oberland	d Approved  m brand Ned 5.	
2	Bahasa: Pastikan air blow berfungsi dengan baik sehingga kotoran bisa keluar dari botol.	AVEI T	4		Per al exercise de la constante de la constant				TAMPON PRIN	
	English: Put 6 pcs bottles that have been checked into the jig.						3	13	TING	
3	Bahasa: Masukkan 6 pcs botol yang telah di cek ke dalam jig.		0,5				Michigal Educates 197			

Version	Release Date	Author	Approver	Description of change
1	As Per DIM Released	Jannaturrum	I Ismo Hadi Sukoco	This is initial released in DIM. Actual update when upload to DIM is on Revision 3 (previous history refer to CSV-14-062-14005).

**DHILIDS** 

1



Bahasa: Ambil dormal dan rakit dormal dengan botol. Pastikan tidak ada rambut, tidak ada serangga, dan nomor hole yang di gunakan benar.

English: Put the bottle to conveyer for the next process.

Bahasa: Lalu letakkan botol ke conveyor untuk di proses pada station packing.




5

Selalu mengutamakan keselamatan, Selalu bekerja dengan hati-hati.

Supplier-customer relation ship always check the result of work from the provious process and check the result our work before being transferred to the next process.

QUALITY CONCERN: Supplier - Customer relation ship / Selalu memeriksa hasil pekerjaan dari proses sebelumnya dan memeriksa hasil pekerjaan kita sebelum diberikan ke proses selanjutnya.



Ī	Version	Release Date	Author	Approver	Description of change
	1	As Per DIM Released	Jannaturrum	Ismo Hadi Sukoco	This is initial released in DIM. Actual update when upload to DIM is on Revision 3 (previous history refer to CSV-14-062-14005).



CELL	. / AREA : MAIN ASSEMBLY	CYCLE TIME (second)		TAKT TIME	SWIP	SWIP SYMBOL	QUALITY CHECK	SAFETY					
STA	FION: STATION 3		24		6,5	6							
No	Job Element Activity	Picture	MAN AUTO WALK				PP	E and Standard La	avout				
1	English: Buy off the sticker A-box before use. If pass, put the A-box sticker that has an IQ stamp in the barcode FA. Take the sticker A-box and paste it in front of the A-box then fold the A-box to the pattern.  Bahasa: Buy off A-box stikcer sebelum digunakan. Jika pass, letakkan A-box sticker yang stempel IQ di FA barcode. Ambil A-box stiker dan tempel di depan A-box lalu lipat A-box sesuai pola.	PHILIPS  BENEFIT BENEF	0,5			Think safety, work safety prioritizing safety, always working carefully. SAFETY FIRST: Think Safety, Work Safety Selalu mengutamakan keselamatan, Selalu bekerja dengan hati-hati.  Supplier-customer relation ship always check the result of work from the							
2	English: Take the bottle from the conveyor, and then check the laser visual and DFU, arrange it into a box (1 box = 120 pcs, 1 layer = 40 pcs), put it into the layer box after full 1 layer.  Bahasa: Ambil botol dari konveyor, dan kemudian cek visual laser dan DFU, susun ke dalam box (1 box =120 pcs, 1 layer=40 pcs), masukan ke layer box setelah penuh 1 layer.					provious process and check the result our work before being transferred to the next process.  QUALITY CONCERN: Supplier - Customer relation ship / Selalu memeriksa hasil pekerjaan dari proses sebelumnya dan memeriksa hasil pekerjaan kita sebelum diberikan ke proses selanjutnya.				nsferred to nemeriksa			
3	English: Put the bottles neatly to avoid missing quantity and make sure the bottles are assembled with complete parts there is no insect and hair contamination in the dormal and bottle.  Bahasa: Letakkan botol dengan rapi untuk menghindari kuantitas yang hilang dan pastikan botol terakit dengan bagian yang komplit tidak ada serangga dan kontaminasi rambut pada dormal dan botol.					PHILIPS	STANDARD I	ASSAL No.	With man h Jan	TAMPON PRINTING			
4	English: Make sure operator production area station 4. Before putting the Abox on the pallet, the operator should be check to drawing pallet on the monitor. To avoid complaints from customers.  Bahasa: Pastikan operator production area station 4. Sebelum meletakkan Abox ke pallet, operator harus mengecek gambar pallet yang ada di layar, untuk menghindari komplain dari pelanggan.	The Management of the Control of the	0,5	0,5	1	Subject Manager No. 1 Marie		1 Authorited Sharkson County C					
							Description						

Version	Release Date	Author	Approver	Description of change
1	As Per DIM Released	Jannaturrum	Ismo Hadi Sukoco	This is initial released in DIM. Actual update when upload to DIM is on Revision 3 (previous history refer to CSV-14-062-14005).

Document ID:8102002518 Version: 2 ARIS Template ID: PE\_006250 ARIS Template Version: 3



CELL	/ AREA : MAIN ASSEMBLY	_	CLE TIME	TAKT TIME	TAKT TIME SWIP		QUALITY CHECK	SAFETY	
STAT	ION : STATION 4  Job Element	24		6,5	6		$\Diamond$		
No	Activity	Picture	MAN	AUTO WAI	к	PPI	E and Standard Lay	out -	
Bahasa: Ambil teat 1 hole galaxy lalu gunakan air blow. Rakit teat dengan screw ring. Pastikan teat yg di gunakan benar.  Gunakan sarung tangan untuk menghindari kontaminasi.  SAFETY FIRST: Think Safe Selalu mengutamakan kes Supplier-customer relatio provious process and che the next process.		work safety prioritizing safety, always working carefully. Think Safety, Work Safety Itamakan keselamatan, Selalu bekerja dengan hati-hati. Tomer relation ship always check the result of work from the The cess and check the result our work before being transferred to The cess. The cess.							
2	English: Make sure the teat and screw ring are assembled properly.  Bahasa: Pastikan teat dan screw ring di rakit dengan benar.	NOT GOOD  Test and screening assembly with properly	1		hasil p	•	es sebelumnya dan n ises selanjutnya.	• •	
3	English: Take the screw ring assembly, use the air blow on the inside and outside of the screw ring and dormal cap to avoid insects and hair. Then close screw ring with a dormal cap. Ensure the dormal cap that is used is correct according to BOM list (with hole or without hole).  Bahasa: Ambil rakitan screw ring, gunakan air blow pada bagian dalam dan luar screw ring dan dormal cap untuk menghindari serangga dan rambut. Lalu tutup screw ring dengan dormal cap. Pastikan dormal cap yang di gunakan benar sesuai dengan BOM list (dengan lubang atau tanpa lubang).		3			oris o	OF 1	12 Northead Workship Seathway 6,5 acc 0 553	AMPON PRINTING

Version	Release Date	Author	Approver	Description of change
1	As Per DIM Released	Jannaturrum	Ismo Hadi Sukoco	This is initial released in DIM. Actual update when upload to DIM is on Revision 3 (previous history refer to CSV-14-062-14005).

Document ID:8102002518 Version: 2 ARIS Template ID: PE\_006250 ARIS Template Version: 3