
온도/습도/조도 Sensor Module



1. 사양

1.1. Description

온/습도 센서는 온도와 습도를 측정하는 센서이다. 온도계나 습도계를 보면 특정 부분을 통해 온도나 습도의 정도를 표시해 주는 것을 보았을 것이다. 다만, 온/습도 센서의 경우 이렇게 받아들인 정보를 하드웨어를 통하여 받아들여 디지털화된 결과를 도출한다.

조도 센서는 쉽게 말해 빛의 양을 측정하는 센서이다. 사용 예로, 요즘 스마트폰을 보면 사진 찍을 때 빛의 양을 조절해주는 기능이 있는데, 빛의 양이 어느 정도인지 확인하기 위하여 조도 센서가 쓰인다. 혹은, 주변이 어두운 경우 스마트폰에서 자동으로 LCD의 밝기를 더 밝게 조절하는 기능에도 사용된다. 측정하는 방법은 빛의 세기에 따라 저항 값이 변하므로 전압 값을 측정하여 이를 수치화 하면 그 정도를 알 수 있도록 한다. 조도 센서는 동작 방식이나 구성에 따라 다양한 종류가 있다.

이 모듈은 빛을 검출할 수 있는 포토 다이오드와, CDS 센서 그리고 온/습도를 검출 할수 있는 SH11 센서가 장착된 모듈이다. 포토 다이오드와 CDS센서는 A/D 변환을통하여 검출 되고 온/습도 센서는 I2C를 이용하여 검출 한다. 자세한 타이밍이나 검출방법은 제공하는 데이터시트를 참조 하기 바란다. 동작 전압은 5V 이다.

1

1.2. 구성

- 1 x Sensor Module
- 1 x Power Cable


Module Cable

1 x RaspberryPi Adapter Module(별도구매)

2. User Guide

2.1. 결선

모듈 별 결선 방법은 다음의 그림 및 표와 같다.



2

Module	Raspberry Pi	Sensor
Pin	Analog In0 S	ILUM PD_OUT
Pin	Analog In1 S	ILUM CDS_OUT
Pin	GPIO6	TEMP SCK
Pin	GPIO12	TEMP DATA

모듈의 장치 및 회로에 대한 상세한 내용은 데이터시트 및 회로도를 참고한다. 2핀 전원 케이블을 사용하여 라즈베리파이 어댑터의 +5V 핀과 GND핀에 연결하고 J3 또는 J4의 전원 컨넥터와 연결한다. 이 때, 화살표로 표시된 핀이 전원이며, 나머지 한 핀이 GND 이다.

2.2. 예제프로그램

각 센서를 통해 측정한 값은 어댑터 보드를 통해 라즈베리파이로 전달되어 주기적으로 표시한다. 조도 값은 밝을수록 수치가 높게 측정된다.

• lib_sensor.h

```
#ifndef __LIB_SENSOR_H__
#define __LIB_SENSOR_H__
#include <stdio.h>
#include <string.h>
#include <errno.h>
#include <wiringPi.h>
#include <wiringPiSPI.h>
#define CS_MCP3208
                        8
                                                 //GPIO 8
#define SPI_CHANNEL
                        0
                                                 //SPI Channel
#define SPI_SPEED
                        1000000
                                                 //spi speed
#define SET_DATA()
                        digitalWrite(SDA, 1)
#define CLR_DATA()
                        digitalWrite(SDA, 0)
#define SET_SCK()
                         digitalWrite(SCK, 1)
```

3

Sensor Module

```
#define CLR_SCK()
                        digitalWrite(SCK, 0)
#define READ_DATA()
                        digitalRead(SDA)
#define READ_SCK()
                        digitalRead(SCK)
#define SCK
                        6
#define SDA
                        12
#define NOACK 0
#define ACK
                1
                                                     Code(command)
                                         // Addr
                                                                        r/w
                                                         0001
#define MEASURE_TEMP
                                 0x03
                                         // 000
                                                                          1
#define MEASURE_HUMI
                                 0x05
                                         // 000
                                                         0010
                                                                          1
#define READ_STATUS_REG
                                 0x07
                                         // 000
                                                         0011
                                                                          1
#define WRITE_STATUS_REG
                                 0x06
                                         // 000
                                                         0011
                                                                          0
#define RESET
                                         // 000
                                                                          0
                                 0x1e
                                                         1111
enum { TEMP, HUMI };
void SHT11_Init (void);
void Connection_reset (void);
void Transmission_start (void);
float get_SHT11_data (unsigned char type);
unsigned char Write_byte (unsigned char value);
unsigned char Read_byte (unsigned char ack);
unsigned char Measure (unsigned short *p_value,
unsigned short *p_checksum,
                                unsigned char mode);
void calc_SHT11 (unsigned short p_humidity ,unsigned short p_temperature);
int ReadMcp3208ADC(unsigned char adcChannel);
#endif /* __LIB_SENSOR_H__ */
```

• lib_sensor.c

#include "lib_sensor.h"

```
float
        val_temp, val_humi;
unsigned short SHT11_humi, SHT11_temp;
unsigned short error, checksum;
unsigned char sensing_type;
static void I2C_data_output (void) { pinMode(SDA, OUTPUT); }
static void I2C_data_input (void)
                                   { pinMode(SDA, INPUT); }
static void I2C_sck_output (void)
                                   { pinMode(SCK, OUTPUT); }
static void I2C_sck_input (void)
                                   { pinMode(SCK, INPUT); }
static void SET_I2CDATA_PIN (void) { digitalWrite(SDA, 1); }
static void CLR_I2CDATA_PIN (void) { digitalWrite(SDA, 0); }
static void SET_I2CSCK_PIN (void) { digitalWrite(SCK, 1); }
static void CLR_I2CSCK_PIN (void) { digitalWrite(SCK, 0); }
static int READ_I2CDATA_PIN (void){ return digitalRead(SDA); }
static int READ_I2CSCK_PIN (void) { return digitalRead(SCK); }
void SHT11_Init (void)
        I2C_data_output ();
                                            // DDRF |= 0x02;
        I2C_sck_output ();
                                   // DDRF |= 0x01;
        Connection_reset ();
}
void Connection_reset (void)
        unsigned char i;
        SET_DATA();
                                                     // Initial state
        CLR_SCK();
                                                     // Initial state
        delayMicroseconds(1);
        for (i=0; i<9; i++) {
                                            // 9 SCK cycles
                 SET_SCK();
                 delayMicroseconds(1);
        CLR_SCK();
```

```
delayMicroseconds(1);
        }
}
void Transmission_start (void)
                                        //Initial state
        SET_DATA();
        CLR_SCK();
                                         //Initial state
        delayMicroseconds(1);
        SET_SCK();
        delayMicroseconds(1);
        CLR_DATA();
        delayMicroseconds(1);
        CLR_SCK();
        delayMicroseconds(1);
        SET_SCK();
        delayMicroseconds(1);
        SET_DATA();
        delayMicroseconds(1);
        CLR_SCK();
}
float get_SHT11_data (unsigned char type)
{
        sensing_type
                          =
                                  type;
                          0;
        error
        if (sensing_type == HUMI) {
```

```
// measure humidity
                         +=
                                 Measure (&SHT11_humi, &checksum, HUMI);
                error
                if (error != 0)
                                          // [Error] connection reset
                         Connection_reset ();
                else
                                          // Calculate humidity, temperature
                         calc_SHT11 (SHT11_humi, SHT11_temp);
                return
                        val_humi;
        }
        else if (sensing_type == TEMP) {
                // measure temperature
                error
                                 Measure (&SHT11_temp, &checksum, TEMP);
                if (error != 0)
                                          // [Error] connection reset
                         Connection_reset ();
                                          // Calculate humidity, temperature
                else
                         calc_SHT11 (SHT11_humi, SHT11_temp);
                return
                         val_temp;
        }
        else {
                return 0;
        }
unsigned char Measure (unsigned short *p_value, unsigned short *p_checksum,
                         unsigned char mode)
{
        unsigned short error
                                          0;
        unsigned short SHT11_msb, SHT11_lsb;
        switch (mode)
                                                  //send command to sensor
                case TEMP:
                                          Write_byte (MEASURE_TEMP);
                         error
                         break;
                case HUMI:
```

```
error
                                           Write_byte (MEASURE_HUMI);
                          break;
                 default:
                          break;
        }
        if (error != 0)
                 return error;
        I2C_data_input ();
        while (READ_DATA());
        I2C_data_input();
        SHT11_msb
                                  Read_byte (ACK); // read the first byte (MSB)
        SHT11_lsb
                                  Read_byte (ACK); // read the second byte (LSB)
        *p_value =
                         (SHT11_msb * 256) + SHT11_lsb;
        *p_checksum
                                  Read_byte (NOACK);
                                                            // read checksum
        return error;
}
unsigned char Write_byte (unsigned char value)
        unsigned char i, error
                                           0;
        I2C_data_output ();
        for (i=0x80; i>0; i/=2)
                 if (i & value)
                                  SET_DATA ();
                                  CLR_DATA ();
                 else
                 delayMicroseconds(1);
                 SET_SCK ();
                 delayMicroseconds(1);
                 CLR_SCK ();
                 delayMicroseconds(1);
        }
```

```
SET_DATA ();
        I2C_data_input ();
        delayMicroseconds(1);
        SET_SCK ();
                          READ_DATA ();
        error
        CLR_SCK ();
        I2C_data_output ();
        return error;
unsigned char Read_byte(unsigned char ack)
        unsigned char i, val
                                           0;
        I2C_data_input ();
        SET_DATA();
        delayMicroseconds(1);
        for (i=0x80; i>0; i/=2)
                 SET_SCK();
                 delayMicroseconds(1);
                 if (READ_DATA())
                          val = (val | i);
                 CLR_SCK();
                 delayMicroseconds(1);
        }
        I2C_data_output();
        if (ack) CLR_DATA();
        else
                          SET_DATA();
        SET_SCK();
        delayMicroseconds(1);
```

```
CLR_SCK();
         delayMicroseconds(1);
         SET_DATA();
         return val;
}
void calc_SHT11 (unsigned short humidity, unsigned short temperature)
         const float C1
                                   -2.0468;
                                                     // for 12 Bit
                                                     // for 12 Bit
         const float C2
                                   0.0367;
         const float C3
                                   -0.0000015955; // for 12 Bit
                          =
         const float T1
                                   0.01;
                                                              // for 12 Bit
         const float T2
                                   0.00008;
                                                              // for 12 Bit
                          =
         float rh_lin;
                                   // Relative Humidity
         float rh_true;
                                   // Humidity Sensor RH/Temperature compensation
         float t_C;
                                            // Temperature
         float rh =
                          (float)humidity;
         float t
                                   (float)temperature;
         t_C
                                            ((t * 0.01) - 40.1) - 5;
         rh_lin
                                   (C3 * rh * rh) + (C2 * rh) + C1;
                          (t_C - 25) * (T1 + (T2 * rh)) + rh_lin;
         rh_true =
         if (rh_true > 100) rh_true = 100;
         if (rh_true < 0.1) rh_true = 0.1;
         val_temp
                                   t_C;
         val_humi=
                          rh_true;
}
int ReadMcp3208ADC(unsigned char adcChannel)
```

```
unsigned char buff[3];
int nAdcValue = 0;

buff[0] = 0x06 | ((adcChannel & 0x07) >> 2);
buff[1] = ((adcChannel & 0x07)<6);
buff[2] = 0x00;

digitalWrite(CS_MCP3208,0); //low cs Active

wiringPiSPIDataRW(SPI_CHANNEL, buff, 3);

buff[1] = 0x0F & buff[1];
nAdcValue = (buff[1]<<8) | buff[2];

//spi chip Select command
digitalWrite(CS_MCP3208, 1);

return nAdcValue;
}
```

sensor.c

```
#include "lib_sensor.h"

volatile float temp;
volatile float humi;

int main (void)
{
    int nCdsChannel = 0;
    int nPhotoCellChannel = 1;

    int nCdsValue = 0;
    int nPhotoCellValue = 0;
    int nPhotoCellValue = 0;
```

```
fprintf(stdout,"Not start wiringPi: %s₩n",strerror(errno));
        return 1;
}
if(wiringPiSPISetup(SPI_CHANNEL, SPI_SPEED) == -1) {
        fprintf(stdout, "wiringPiSPISetup Failed: %s₩n", strerror(errno));
        return 1;
}
pinMode(CS_MCP3208, OUTPUT);
SHT11_Init();
while (1)
{
        Transmission_start();
        temp = get_SHT11_data (TEMP); // Sensing Temp
        delay(100);
        Transmission_start();
        humi = get_SHT11_data (HUMI); // Sensing Humi
        delay(100);
        printf("Temp = %2.2f [C], Humi = %2.2f [%]₩n", temp, humi);
        //sensorRead
        nCdsValue = ReadMcp3208ADC(nCdsChannel);
        nPhotoCellValue = ReadMcp3208ADC(nPhotoCellChannel);
        printf("CSD Sensor Value = %u₩n", nCdsValue);
        printf("Photocell Sensor Value = %u₩n", nPhotoCellValue);
        delay(500);
return 0;
```