

SOP — Work Order Lifecycle

Document ID: APEL-SOP-MNT-213 | Owner: Maintenance | Revision: 5.5

This page defines the task-specific controls for work initiation.

Work initiation

- Operator notification
- Preventive plan
- Inspection finding
- Failure event
- Project requirement

Priority levels

This page defines the task-specific controls for priority levels.

Priority levels

Priority	Meaning
P1	Immediate safety/process risk
P2	High reliability or integrity risk
P3	Planned maintenance
P4	Minor improvement

Planning fields

This page defines the task-specific controls for planning fields.

Planning fields

- Craft
- Duration
- Spare parts
- Special tools
- Permit needs
- Shutdown dependency

Execution evidence

This page defines the task-specific controls for execution evidence.

Execution evidence

- Actual finding
- Measurements
- Photographs
- Parts replaced
- Failure mode
- Temporary repair

Closeout

This page defines the task-specific controls for closeout.

Closeout

- Correct asset
- Failure code
- Completion date
- Technician sign-off
- Supervisor review