

# SOP — CDU-4 Planned Shutdown

Document ID: APEL-SOP-OPS-202 | Owner: Operations | Revision: 8.4

This page defines the task-specific controls for shutdown planning.

## Shutdown planning

- Agree shutdown window.
- Review intervention list.
- Confirm isolation plans.
- Check downstream storage.

## Feed reduction

This page defines the task-specific controls for feed reduction.

### Feed reduction

- Reduce crude feed in stages.
- Adjust furnace duty.
- Manage reflux and stripping steam.
- Monitor column differential pressure.

## Depressurization

This page defines the task-specific controls for depressurization.

### Depressurization

- Stop feed.
- Secure heating.
- Isolate equipment.
- Depressurize through approved systems.
- Drain/purge where authorized.

## Post-shutdown checks

This page defines the task-specific controls for post-shutdown checks.

### Post-shutdown checks

- Leak survey
- Pump condition check
- Valve-position verification
- Furnace visual check
- Instrument status review

## Restart record

This page defines the task-specific controls for restart record.

### Restart record

- Open work orders
- Temporary repairs
- Instrument bypasses
- Outstanding inspections
- Management decisions