

SOP — Energy Isolation and Lockout

Document ID: APEL-SOP-HSE-232 | Owner: HSE | Revision: 8.7

This page defines the task-specific controls for energy identification.

Energy identification

- Electrical
- Pressure
- Hydraulic
- Pneumatic
- Thermal
- Rotational

P-102 boundary

This page defines the task-specific controls for p-102 boundary.

P-102 boundary

- M-102 electrical supply
- Process suction isolation
- Process discharge isolation
- Drain/vent as required
- Stored rotational energy

Lockout

This page defines the task-specific controls for lockout.

Lockout

- Individual locks where required.
- Group lockbox for multi-person work.
- Formal exception for lock removal.

Zero-energy verification

This page defines the task-specific controls for zero-energy verification.

Zero-energy verification

- Absence-of-voltage test
- Pressure confirmation
- Drain verification
- Approved try-start where safe

Restoration

This page defines the task-specific controls for restoration.

Restoration

- Work complete
- Guards installed
- Tools removed
- Locks cleared
- Line-up restored
- Operations acceptance