# TOOLBOX TALK #20

## WORKING IN LOW-LIGHT CONDITIONS

### ⚠️ WHY THIS MATTERS

As winter approaches, daylight hours are getting shorter, creating reduced visibility during the workday.

Low-light conditions increase the risk of workplace incidents, especially those involving moving equipment, vehicles, and slips, trips, and falls. These incidents can happen when workers are difficult to see or hazards go unnoticed.

Always remain visible, stay alert, and take extra precautions when working in low-light conditions.

---

### 🦺 HIGH-VISIBILITY REFLECTIVE VESTS

All employees are required to wear their Ridge Rock-provided reflective safety vest while on a jobsite.

- Wear your reflective vest at all times.
- High-visibility shirts alone do not meet Ridge Rock PPE requirements.
- Keep reflective strips clean and visible.
- Wear your vest over jackets, hoodies, and winter clothing.
- Replace damaged, faded, or heavily worn vests.
- Continue wearing all other required PPE.

**YOUR REFLECTIVE VEST MUST REMAIN VISIBLE AT ALL TIMES.**

---

### 💡 PROPER LIGHTING

- Make sure work areas, walkways, and equipment operating areas have adequate lighting.
- Use appropriate work lights when natural daylight is insufficient.
- Position lights to avoid blinding drivers or equipment operators.
- Watch for shadows, uneven ground, and hazards that may be difficult to see.
- Notify your foreman immediately if additional lighting is needed.

**DO NOT CONTINUE WORKING IF POOR LIGHTING MAKES THE AREA UNSAFE.**

---

### 🚧 VEHICLES & HEAVY EQUIPMENT

- Stay out of equipment blind spots.
- Never assume an operator can see you.
- Make eye contact or establish clear communication before approaching equipment.
- Stay clear of backing vehicles and moving machinery.
- Follow established spotter and backing procedures.
- Reduce speed and adjust equipment operation to visibility conditions.
- Check headlights, work lights, and warning devices before operating equipment.

**JUST BECAUSE YOU CAN SEE THE EQUIPMENT DOES NOT MEAN THE OPERATOR CAN SEE YOU.**

---

### 🚦 WORKING NEAR TRAFFIC

- Stay within designated work areas and behind established traffic control barriers.
- Follow all traffic control signs, cones, and directions from traffic control personnel.
- Never enter active traffic lanes without proper protection and authorization.
- Stay alert for vehicles entering or passing through the work zone.
- Never assume drivers can see you, especially in low-light conditions.
- Notify your foreman immediately if traffic control or visibility conditions become unsafe.

**ALWAYS STAY ALERT WHEN WORKING NEAR MOVING TRAFFIC.**

---

### 👷 FOREMEN — WATCH YOUR CREW

Foremen must monitor lighting and visibility as conditions change throughout the workday.

Make sure employees are wearing their reflective safety vests correctly and that work areas are adequately illuminated.

Pay particular attention to equipment movement, backing operations, and employees working near traffic.

**STOP OR ADJUST WORK IF VISIBILITY BECOMES UNSAFE.**

---

### ✅ REMEMBER

**WEAR YOUR REFLECTIVE SAFETY VEST.**

**MAKE SURE YOU CAN SEE AND BE SEEN.**

**STAY OUT OF EQUIPMENT BLIND SPOTS.**

**USE PROPER LIGHTING.**

**REPORT UNSAFE VISIBILITY TO YOUR FOREMAN.**

As daylight hours get shorter, stay alert and take the extra precautions needed to protect yourself and your coworkers.

**Work Safe. Go Home Safe.**

---

**RIDGE ROCK LLC**

**CHARLA DE SEGURIDAD #020**

**TRABAJO EN CONDICIONES DE POCA LUZ**

### ⚠️ ¿POR QUÉ ES IMPORTANTE?

A medida que se acerca el invierno, los días tienen menos horas de luz, lo que reduce la visibilidad durante la jornada laboral.

Las condiciones de poca luz aumentan el riesgo de accidentes laborales, especialmente aquellos relacionados con maquinaria en movimiento, vehículos, resbalones, tropiezos y caídas. Estos incidentes pueden ocurrir cuando es difícil ver a los trabajadores o cuando los peligros pasan desapercibidos.

Manténgase siempre visible, alerta y tome precauciones adicionales cuando trabaje en condiciones de poca luz.

---

### 🦺 CHALECOS REFLECTANTES DE ALTA VISIBILIDAD

Todos los empleados deben usar el chaleco de seguridad reflectante proporcionado por Ridge Rock mientras se encuentren en una obra.

- Use su chaleco reflectante en todo momento.
- Las camisetas de alta visibilidad por sí solas no cumplen con los requisitos de EPP de Ridge Rock.
- Mantenga las franjas reflectantes limpias y visibles.
- Use su chaleco sobre chaquetas, sudaderas y ropa de invierno.
- Reemplace los chalecos dañados, desteñidos o muy desgastados.
- Continúe usando todo el demás EPP requerido.

**SU CHALECO REFLECTANTE DEBE PERMANECER VISIBLE EN TODO MOMENTO.**

---

### 💡 ILUMINACIÓN ADECUADA

- Asegúrese de que las áreas de trabajo, pasillos y zonas donde opera maquinaria tengan suficiente iluminación.
- Use luces de trabajo apropiadas cuando la luz natural sea insuficiente.
- Coloque las luces para evitar encandilar a conductores u operadores de maquinaria.
- Tenga cuidado con las sombras, el terreno irregular y los peligros que puedan ser difíciles de ver.
- Avise inmediatamente a su capataz si se necesita iluminación adicional.

**NO CONTINÚE TRABAJANDO SI LA MALA ILUMINACIÓN HACE QUE EL ÁREA SEA INSEGURA.**

---

### 🚧 VEHÍCULOS Y MAQUINARIA PESADA

- Manténgase fuera de los puntos ciegos de la maquinaria.
- Nunca suponga que un operador puede verlo.
- Haga contacto visual o establezca comunicación clara antes de acercarse a la maquinaria.
- Manténgase alejado de vehículos que retroceden y maquinaria en movimiento.
- Siga los procedimientos establecidos para señalistas y maniobras de retroceso.
- Reduzca la velocidad y adapte la operación de maquinaria a las condiciones de visibilidad.
- Revise los faros, luces de trabajo y dispositivos de advertencia antes de operar maquinaria.

**QUE USTED PUEDA VER LA MAQUINARIA NO SIGNIFICA QUE EL OPERADOR PUEDA VERLO.**

---

### 🚦 TRABAJO CERCA DEL TRÁ